




## **ATTACHMENT 2**

**AIRWORTHINESS GROUP CHAIRMAN'S FACTUAL REPORT**

**LAX-02-GA-201**

# LAX02GA201



N. Flagg 07-01-02

1	Wing - Left	13	Propeller Assembly	26	Tail
2	Propeller	14	Propeller	27	Main Gear w/Tire
3	Propeller	15	Propeller Assembly	28	Main Gear w/Tire
4	Propeller	16	Wing Section - Right	29	Farthest North Debris
5	Propeller	17	Initial Impact	30	Fuselage Skin - Aft Left Paratrooper Door
6	Propeller	18	Right Elevator (Outboard)	31	Cockpit area and Forward Cargo Compartment
7	Propeller Assembly	19	Start of Main Impact Site	32	Nose Gear Strut
8	Engine SN A101267	20	Landing Gear Strut	33	Retardant Tank Structure
9	Propeller Assembly/Left Outer Wing	21	Right Horizontal Stabilizer (Inboard)	34	Large Section Of Fuselage Skin
10	Engine	23	Upper Aft Cargo Ramp	35	Section of APU
11	Engine SN A100843	24	Wires/Fuselage Skin	36	Main Gear w/Tire
12	Engine SN AE101504/Bottom of Center Wing	25	Right Elevator with Trim Tab	37	Nose Gear and Axial
				38	Farthest East Debris - APU