



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

June 20, 2016

AIRWORTHINESS

Group Chairman's Factual Report

ANC15MA041

**Appendix A – Figures
(4 pages)**




Figure 1 – de Havilland DHC-3 Otter with turbine engine conversion



Figure 2 – Main wreckage site, aerial view



Figure 3 – Switch panel with TAWS switch from N270PA wreckage



Figure 4 – Altimeter from N270PA wreckage



Figure 5 – Center quadrant from N270PA wreckage




Figure 6 – PT6A-135A engine from N270PA



Figure 7 – HC-B3TN-3DY Propeller from N270PA