



04.18.2017 12:49



04.18.2017 13:27



04.18.2017 14:13



04.18.2017 18:23





04.19.2017 16:38





04.21.2017 12:22





04.21.2017 12:30





04.24.2017 16:45





04.24.2017 16:45





04.24.2017 16:49





04.24.2017 16:49



Evidence to support Flowline from Coors 6-14Ji was not excavated from the wellhead to the cut end at the house. I would hope this photo log is evidence enough.

- 1) Photo 013(2) is looking from south of the home to the well. Notice the building trusses on the right side of photo and time stamp of 04.18.2017
- 2) Photo 019 shows Abandoned flowline and 1" PE return line on 04.18.2017
- 3) Photo 039 is looking from well to home. Notice line marked on right. This was the active flowline from the wellhead. Again notice trusses to the left and date of 04.18
- 4) Photo 103 shows the initial excavation just south of the house on 4.18. Notice no open excavation leading to it.
- 5) Photo DSCN1521 shows excavation that exposed lines south of house. Notice date stamp 04.19.
- 6) Photo DSCN1541 show wellhead of Coors 6-14 Ji on 04.21.2017. Abandoned flowline and return 1" in bottom left of photo. No evidence of excavation. Notice trusses beyond for reference.
- 7) Photo DSCN1567 is looking towards well from parking lot south of house. Notice line markers, these relate to marking of abandoned line from wellhead to house. Notice trusses for reference. No indication of excavation on 04.24.2017.
- 8) Photo DSCN1568 is taken from same point as DSCN1567 described above. This is looking towards house. Initial excavation as soon in #4 above is near the two men in white hard hats on the right. Notice line marked under parking lot, not excavated.
- 9) Photo DSCN1572 looking from original excavation south of house to parking lot. Notice elevated work structure in parking lot. Same structure as seen in #8 above
- 10) Photo DSCN1573 taken from north end of elevated structure towards house. Yellow lines indicate abandoned lines from 6-14 Ji (right) and 6-14 (left).

Photo DSCN1554 is from the Coors 6-13, note the lines in the bottom right. These are the improperly abandoned flowline and 1" PE return line at this well that we discussed on 9/4/2019.