Jones Patrick		
From: To: Cc: Subject: Attachmen	Epperson Joe Jones Patrick Budinski Michael WPR11LA069 Peoria AZ ts:	<b>Sent:</b> Mon 1/3/2011 07:55
January 3, 20	11	
Peoria, Arizon	a	
December 1,	2010	
Saber Trike U	Itralight, N765MH	
WPR111LA06	9	
Patrick Jones,	ASI WPR	
Two control c	ables.	
Fractures in the and deformat	ne left control cable were examined with a stereo micr ion patterns consistent with overstress separations. No	oscope. The individual wire fractures displayed fracture features of indications of preexisting fatigue or corrosion were noted.
Joe Epperson		
NTSB Sr Meta	llurgist	