



"TAKE YOUR CESSNA HOME
FOR SERVICE AT THE SIGN
OF THE CESSNA SHIELD"

MULTIENGINE CUSTOMER CARE SERVICE INFORMATION LETTER

MARKETING DIVISION / CESSNA AIRCRAFT COMPANY / WICHITA, KANSAS 67201 / CABLE ADDRESS - CESSCO WICHITA

August 1, 1979

ME79-28

SUBJECT: TRIM TAB ACTUATOR INSPECTION

AIRCRAFT APPLICABILITY: 300-400 Series
(Except 337)

As currently outlined in the Service Manuals (servicing section, lubrication diagram) trim tab actuators are to be disassembled, inspected, and serviced every 1500 hours.

Because of past field experience this required inspection/lubrication interval has been changed to 1000 hours or three years which ever comes first.

Therefore, aircraft which currently have more than 1000 hours total time, or three years in service are to have the trim tab actuators removed and serviced within the next 100 hours of operation.

This change in inspection/lubrication interval will be added to all Service/Maintenance Manuals at the next revision.