

Coast Guard
Port State Information Exchange
(PSIX)

Fourteen (14) pages total including this cover



Printer Friendly Page

Vessel Information

Vessel
ANDREW J. BARBERI
VIN 629314
Hull Number
Flag USA
Call-Sign WYR3370
Year Built 1981

Vessel Particulars

Service
Passenger (More Than 6)
Length 310.0 ft
Breadth 70.0 ft
Depth 20.7 ft
Alternate VINs
IMO Number

Service Information

Service Status In Service
Out of Service Date
Last removed from service by: ACTIVITIES NEW YORK

Tonnage Information

Deadweight 3335
Gross Tonnage (GRT) 2268
Net Tonnage (NRT) 2268
Gross Tonnage (GT ITC)

Cargo Authority:

Vessel Documents and Certifications

Document	Agency	Date Issued	Expiration Date
CERTIFICATE OF DOCUMENTATION	USCG	September 11, 2003	September 30, 2004
Certificate of Inspection	USCG	January 15, 2003	January 15, 2004
Certificate of Inspection - Amended	USCG	January 15, 2003	January 15, 2004
Classification Document	ABS	May 14, 2002	July 31, 2007
Certificate of Inspection	USCG	January 17, 2002	January 17, 2003
Certificate of Inspection - Amended	USCG	January 17, 2002	January 17, 2003

Version 2.0



- Welcome
- Vessel Search
- FAQ/Help
- Archive Data
- Quick Jumps:
- Documentation
- Contacts

Certificate of Inspection - Amended
 Classification Document

USCG January 4, 2001 January 4, 2002
 ABS November 29, 1996 May 31, 2002

[Back to Top](#)

Summary of Coast Guard Contacts

Activity USCG Number Zone/Port	Date	Activity Type	Enforcement Incident Description	Cause
1861587 STATEN ISLAND, NY	July 25, 2003	Vessel Inspection		
Deficiency Information				
System		SubSystem		
Fire Fighting		Structural - A Class Divisions		

Description of Deficiency

Inboard FSD on saloon deck, Staten Island end, NJ side missing lock mechanism. Replace and prove proper operation.

Activity USCG

Number Zone/Port	Date	Activity Type	Enforcement Incident Description	SubSystem
1822485 STATEN ISLAND, NY	June 19, 2003	Vessel Inspection		
1775239 STATEN ISLAND, NY	April 17, 2003	Vessel Inspection		
Deficiency Information				
System				SubSystem
Engineering				Diesel Engine (auxiliary)

Description of Deficiency

Replace cracked cover on #2 SSG freshwater cooling flex coupling on discharge side of engine.

Deficiency Information

System
Accommodation/Occupational Safety

SubSystem
Occupational Safety

C

Description of Deficiency

Replace/install guards to all four MDE's salt water pump belts.

Deficiency Information

System
Accommodation/Occupational Safety

SubSystem

Occupational Safety

C

Description of Deficiency

Submit proposal for storage of mooring lines away from rescue boat launching stations.

Deficiency Information

System
Fire Fighting

SubSystem

Ventilation Systems

C

Description of Deficiency

Submit proposal to allow quick access to fire dampers 1-18-01 and 1-18-02 located on top of ladder to engine

Activity USCG Number Zone/Port	Date	Activity Type	Enforcement Incident Description
1729948	STATEN ISLAND, NY January 14, 2003	Vessel Inspection	
1698809	STATEN ISLAND, NY October 30, 2002	Incident Investigation	Marine Casualty, Reportable
1697855	STATEN ISLAND, NY October 24, 2002	Vessel Inspection	
1682809	STATEN ISLAND, NY October 1, 2002	Vessel Inspection	
1671492	STATEN ISLAND, NY September 4, 2002	Vessel Inspection	

Deficiency Information

System

SubSystem

Cause

Engineering

Description of Deficiency

Repair and prove proper operation of #1 SSDG to the satisfaction of attending marine inspector.

Activity USCG Number Zone/Port	Date	Activity Type	Enforcement Incident Description
1652080 STATEN ISLAND, NY	July 25, 2002	Vessel Inspection	
Deficiency Information			
System	SubSystem	Cause	
Electrical		Improper/Lack of Maintenance	

Description of Deficiency

Repair or properly terminate wires on hurricane deck ventilation scoop.

Deficiency Information System	SubSystem	Cause
Fire Fighting	Fire Hydrants	Improper/Lack of Maintenance

Description of Deficiency

Make repairs to hurricane deck fire station housing (wasted).

Deficiency Information System	SubSystem	Cause
Lifesaving	Rescue Boat	Improper/Lack of Maintenance

Description of Deficiency

Place retro on bottom of rescue boats IAW 46CFR Subchpt "W".

Activity USCG	Activity	Enforcement Incident

Number	Zone/Port	Date	Type	Description	Description
1627095	STATEN ISLAND, NY	June 6, 2002	Incident Investigation	Marine Casualty, Reportable	Marine Casualty, Reportable
1624163	STATEN ISLAND, NY	May 30, 2002	Vessel Inspection		
1614347	STATEN ISLAND, NY	May 8, 2002	Incident Investigation	Marine Casualty, Reportable	Marine Casualty, Reportable
1610681	STATEN ISLAND, NY	April 29, 2002	Incident Investigation		
1598360	STATEN ISLAND, NY	March 27, 2002	Vessel Inspection		
1492052	STATEN ISLAND, NY	March 6, 2002	Incident Investigation	Marine Casualty, Reportable	Marine Casualty, Reportable
1491575	STATEN ISLAND, NY	March 4, 2002	Incident Investigation	Marine Casualty, Reportable	Marine Casualty, Reportable
1489531	STATEN ISLAND, NY	February 26, 2002	Incident Investigation	Unverifiable Report of Marine	Unverifiable Report of Marine
1397694	STATEN ISLAND, NY	August 17, 2001	Vessel Inspection		

Description of Deficiency

Deficiency Information

System
Engineering

SubSystem

Cause
Unknown

Description of Deficiency

Deficiency Information

System
Engineering

SubSystem

Cause
Unknown

Description of Deficiency

As a result of normal service, a nipple for the #4 engine governor cracked causing a fuel oil leak.

Deficiency Information System

Accommodation/Occupational Safety

SubSystem

Cause

Unknown

Description of Deficiency

COMPLETE AS BUILT VERIFICATION FOR INSTALLATION OF NEW CONCESSION STAND IAW EXAMINED PLANS AND NYCMI LTR PR-010087. PLANS ARE MAINTAINED IN ANDREW J. BAR VESSEL FILE.

Deficiency Information System

Fire Fighting

SubSystem

Cause

Description of Deficiency

Conduct maintenance to fire doors and test in presence of CG Inspector.

Deficiency Information System

Engineering

SubSystem

Cause

Unknown

Description of Deficiency

governor drive gears worn causing overspeed trips.

Deficiency Information System

Electrical

SubSystem

Cause

Unknown

Description of Deficiency

Insp US passenger ferry lost #2 ship's service generator when overspeed control switch failed due to normal and tear.

Deficiency Information
System
 Engineering

SubSystem

Cause
 Unknown

Description of Deficiency

Inspected US passenger ferry lost #2 main engine due to failure of raw water pump pulley.

Deficiency Information
System
 Engineering

SubSystem

Cause
 Unknown

Description of Deficiency

New York End engine throttles frozen due to ice in air system.

Deficiency Information
System
 Electrical

SubSystem

Cause
 Unknown

Description of Deficiency

No.2 compressor motor overheated.

Deficiency Information
System
 Navigation

SubSystem

Cause

Description of Deficiency

Repair NY end pilot house console lights.

Deficiency Information

System
Engineering
SubSystem
Unknown
Cause
Unknown

Description of Deficiency
REPAIR WASTED VENT SYSTEM IN THE CO2 STORAGE ROOM.

Deficiency Information
System
Lifesaving
SubSystem
Unknown
Cause
Unknown

Description of Deficiency
Replace 1599 identified lifejackets that have glue in fabric prior to next quarterly exam.

Deficiency Information
System
Engineering
SubSystem
Unknown
Cause
Unknown

Description of Deficiency
upper starter pinion hung-up in fly wheel.

Deficiency Information
System
Navigation
SubSystem
Unknown
Cause
Unknown

Description of Deficiency
Vacuum behind behind chart.

Deficiency Information
System
Engineering
SubSystem
Unknown
Cause
Unknown

Description of Deficiency

#1 & #2 engine throttles on NY Pilot house failed.

Deficiency Information

System

Electrical

SubSystem

Cause

Unknown

Description of Deficiency

Circuit breaker failed on No. 1 compressor.

Deficiency Information

System

Navigation

SubSystem

Cause

Description of Deficiency

Complete 2 new compass cards (one for each compass).

Deficiency Information

System

Engineering

SubSystem

Cause

Unknown

Description of Deficiency

Engine air-transfer switch worn.

Deficiency Information

System

Engineering

SubSystem

Cause

Description of Deficiency

Install personnel safety guard over potable water fill pipe heating coils.

Deficiency Information System

Engineering

SubSystem

Cause
Unknown

Description of Deficiency

Loose electrical connector at the #2 main engine governor junction box.

Deficiency Information System

Electrical

SubSystem

Cause
Unknown

Description of Deficiency

LOOSE WIRES WERE FOUND TO THE TERMINAL BLOCK UNDER THE MAIN ENGINE'S CONTR
CONSOLE.

Deficiency Information System

Navigation

SubSystem

Cause

Description of Deficiency

Repair "alarm silence" in NY Pilothouse.

Deficiency Information System

Engineering

SubSystem

Cause
Unknown

Description of Deficiency

REPAIR OR REPLACE BROOKLYN SIDE WINDOWS ON MAIN DECK, EXCESSIVE LEAKS.

Deficiency Information

System

Engineering

SubSystem

Cause

Unknown

Description of Deficiency

REPLACE WASTED INNER BULKHEADS BENEATH SEATS LOCATED MAIN DECK BROOKLYN

Deficiency Information

System

Engineering

SubSystem

Cause

Unknown

Description of Deficiency

The micro-switch that controls the coupling malfunctioned due to frayed wiring.

Deficiency Information

System

Engineering

SubSystem

Cause

Unknown

Description of Deficiency

VSP unit hub assembly unit failed, providing incorrect propulsion/steering feedback resulting in an allision.

Activity USCG

Number Zone/Port

Date

Activity Type

Enforcement Incident Description

132244 STATEN ISLAND, NY May 14, 2001

Incident Investigation

Marine Casualty, Reportable

14863 STATEN ISLAND, NY May 3, 2001

Incident Investigation

Marine Casualty, Reportable

5222 STATEN ISLAND, NY April 5, 2001

Incident Investigation

Marine Casualty, Reportable

143479 STATEN ISLAND, NY November 30, 2000

Incident Investigation

Marine Casualty, Reportable

166201 STATEN ISLAND, NY August 17, 2000

Incident Investigation

Marine Casualty, Reportable

46542	STATEN ISLAND, NY July 7, 2000	Incident Investigation	Marine Casualty, Reportable
118694	STATEN ISLAND, NY July 4, 2000	Incident Investigation	Marine Casualty, Reportable
187616	STATEN ISLAND, NY March 24, 2000	Incident Investigation	Marine Casualty, Reportable
5155	STATEN ISLAND, NY February 4, 2000	Incident Investigation	Marine Casualty, Reportable
29408	STATEN ISLAND, NY January 28, 2000	Incident Investigation	Marine Casualty, Reportable
91232	STATEN ISLAND, NY January 27, 2000	Incident Investigation	Marine Casualty, Reportable
86242	STATEN ISLAND, NY December 7, 1999	Incident Investigation	Marine Casualty, Reportable
90671	STATEN ISLAND, NY October 5, 1999	Incident Investigation	Marine Casualty, Reportable
175504	STATEN ISLAND, NY August 24, 1999	Incident Investigation	Marine Casualty, Reportable
48071	STATEN ISLAND, NY May 20, 1999	Incident Investigation	Marine Casualty, Reportable
112880	STATEN ISLAND, NY April 9, 1999	Incident Investigation	Marine Casualty, Reportable
119644	STATEN ISLAND, NY December 15, 1998	Incident Investigation	Marine Casualty, Reportable
139803	STATEN ISLAND, NY October 9, 1998	Incident Investigation	Marine Casualty, Reportable
24854	STATEN ISLAND, NY September 30, 1998	Incident Investigation	Marine Casualty, Reportable
72291	STATEN ISLAND, NY August 27, 1998	Incident Investigation	Marine Casualty, Reportable
54178	STATEN ISLAND, NY August 14, 1998	Incident Investigation	Marine Casualty, Reportable
56744	STATEN ISLAND, NY July 24, 1998	Incident Investigation	Marine Casualty, Reportable
93745	STATEN ISLAND, NY July 14, 1998	Incident Investigation	Marine Casualty, Reportable
21013	STATEN ISLAND, NY July 6, 1998	Incident Investigation	Marine Casualty, Reportable
130367	STATEN ISLAND, NY March 24, 1998	Incident Investigation	Marine Casualty, Reportable
58168	STATEN ISLAND, NY March 19, 1998	Incident Investigation	Marine Casualty, Reportable
118283	STATEN ISLAND, NY March 15, 1998	Incident Investigation	Marine Casualty, Reportable
212975	STATEN ISLAND, NY April 17, 1995	Incident Investigation	Marine Casualty, Reportable
19386	STATEN ISLAND, NY April 17, 1995	Incident Investigation	Marine Casualty, Reportable
44765	STATEN ISLAND, NY July 29, 1994	Incident Investigation	Marine Casualty, Reportable



United States
Coast Guard

National Vessel
Documentation Center
Phone: (800) 799-8362

Order Abstract of Title

Page Created: 30 August 2000
Last Modified: 14 May 2002

Disclaimer: www.uscg.mil/disclaim.html
Questions?: psix@comdt.uscg.mil
Phone: (202) 267-6889

Marine Safety Pages:
[Port State Control \(Home Page\)](#)
[Office of Marine Safety](#)

Rehabilitation Act (Section 508):
[Web accessibility concerns?](#)
[DOT Policy regarding web accessibility](#)
Phone: (202) 493-1052