



Exhibit 34- Photo Showing Broken Weld of an Operating Cab Rear Mounting Post on BNSF 9159