



Exhibit 44-Photo Showing Damaged End Sill of the Struck End on HZGX-150 Clip Car