



Exhibit 47-Photo Showing Front Section of Center Sill Severed and Bent on HZGX-150 Clip Car