



Exhibit 51-Photo Showing Damage to Saddle Assemblies on HZGX-150 Clip Car