

Fri, June 03, 2016 07:01:32 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 04/02/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Wright/Harris
Weather: Clear **How Conducted:** Hi-Rail

Date Inspection Uploaded into the Central System: 04/02/2015 06:30:49 PM
Date Inspection Closed by Inspector: 04/02/2015 06:25:58 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments
 Wright inspected from 417.48-517 Harris inspected 517-524.98

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:01:42 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 04/07/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/07/2015 07:43:40 PM
Date Inspection Closed by Inspector: 04/07/2015 07:34:25 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:01:53 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 04/10/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 04/10/2015 03:08:52 PM
Date Inspection Closed by Inspector: 04/10/2015 03:07:49 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

Fri, June 03, 2016 07:02:03 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 04/11/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 04/11/2015 12:35:18 PM
Date Inspection Closed by Inspector: 04/11/2015 12:24:19 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
-------------------	----------------	----------------	-----------	--	--------	--------	----	-----------	--------	------------------------------

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

[Top of Page](#)

Fri, June 03, 2016 07:02:12 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 04/14/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/14/2015 07:52:56 PM
Date Inspection Closed by Inspector: 04/14/2015 07:07:35 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
Comments										

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/14/2015	Installed bolt or bolts	04/14/2015		installed bolts in interlocker
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/14/2015	Installed bolt or bolts	04/14/2015		installed bolts in interlocker
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/14/2015	Installed bolt or bolts	04/14/2015		installed bolts in interlocker
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/14/2015	Installed bolt or bolts	04/14/2015		installed bolts in interlocker
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	04/14/2015	Corr from Trk Mtce Plan	04/28/2015		missing interlocker bolts

Switch Defects
 No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:02:24 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 04/16/2015 **Inspected By:** Printice Allen
Inspection Type: Critical Lead **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/16/2015 08:45:58 PM
Date Inspection Closed by Inspector: 04/16/2015 08:44:26 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK

Track Traversed Information

- NONE -

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:02:37 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 04/17/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/17/2015 05:36:44 PM
Date Inspection Closed by Inspector: 04/17/2015 05:32:27 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/17/2015	Installed bolt or bolts	04/17/2015		

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:02:46 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 04/21/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/21/2015 08:33:07 PM
Date Inspection Closed by Inspector: 04/21/2015 08:25:57 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	466.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	466.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE 01 105	418.00		121C2-121.C2 - Center cracked o	Repaired Before Traffic	04/21/2015	Replaced joint bars	04/21/2015		replaced broke bar
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.20	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/21/2015	Installed bolt or bolts	04/21/2015		put bolts in script joint
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/21/2015	Installed bolt or bolts	04/21/2015		replaced interlocker bolts

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:02:59 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 04/24/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 04/24/2015 08:54:37 PM
Date Inspection Closed by Inspector: 04/24/2015 08:45:45 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:03:13 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 04/28/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/28/2015 10:00:00 PM
Date Inspection Closed by Inspector: 04/28/2015 09:55:08 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.20	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.20	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	419.00		121D1-121.D1 - Less than 2 bolt	Repaired Before Traffic	04/28/2015	Installed bolt or bolts	04/28/2015		
PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 044	418.80		121D2-121.D2 - Less than 1 bolt	Repaired Before Traffic	04/28/2015	Installed bolt or bolts	04/28/2015		

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.51	2766 CROS	77 -023	CROSSOVER 023-042	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.55	2766 YARD	01 -049	NEW TRANSFER TO LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.12	2779 INDU	02 -748	SIDING TO KERMAGIE LEAD	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.16	2767 SIDE	01 -105	SIMN TO SIDING	

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:03:24 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 04/29/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** L.Bennett
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/29/2015 06:56:38 PM
Date Inspection Closed by Inspector: 04/29/2015 06:45:58 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		419.14	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		419.14	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.12	2779 INDU	02 -748	SIDING TO KERMAGIE LEAD	

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:03:33 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 04/30/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 04/30/2015 10:19:57 PM
Date Inspection Closed by Inspector: 04/30/2015 10:09:15 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 061	417.75	418.60	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 061	418.60	418.77	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 022	418.58	418.60	No	BOKENKAMP	PASLAY	#22 W. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 042	417.84	418.60	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 042	418.60	419.05	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2

Track Traversed Information

- NONE -

Comments

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.43	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.47	2766 CROS	77 -023	CROSSOVER 023-#1 MAIN	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.58	2766 CROS	77 -022	CROSSOVER 022	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	418.77	2766 YARD	01 -061	WE 061	Solid Mang. Self Guarding
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 042	418.98	2767 YARD	01 -044	WE 044	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.05	2767 YARD	01 -042	WE 042	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.14	2767 CNRT	01 -600	OLD TRANSFER OFF LITTLE ROCK	Spring-All Rail Extd length

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:04:59 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/01/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 05/01/2015 05:28:21 PM
Date Inspection Closed by Inspector: 05/01/2015 05:18:45 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	434.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	434.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:05:11 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/05/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 05/05/2015 04:04:13 PM
Date Inspection Closed by Inspector: 05/05/2015 03:52:20 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	416.35	418.60	No	BOKENKAMP	HOOK	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	416.35	418.60	No	BOKENKAMP	HOOK	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:05:20 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 05/07/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 05/07/2015 08:37:32 PM
Date Inspection Closed by Inspector: 05/07/2015 08:28:20 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK

Track Traversed Information

- NONE -

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT 01 600	419.00		121C2-121.C2 - Center cracked o	213.98	05/07/2015	Corr from Trk Mtce Plan	05/08/2015		

Switch Defects

No switch defect records found

[PRINT](#)

[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:05:30 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/08/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 05/08/2015 04:27:37 PM
Date Inspection Closed by Inspector: 05/08/2015 04:24:49 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/08/2015	Installed bolt or bolts	05/08/2015		

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:05:39 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/11/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Lorenza Bennett
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 05/11/2015 09:50:50 PM
Date Inspection Closed by Inspector: 05/11/2015 09:44:24 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:05:50 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 05/13/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 05/13/2015 03:36:35 PM
Date Inspection Closed by Inspector: 05/13/2015 03:20:40 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/13/2015	Installed bolt or bolts	05/13/2015		put bolts in interlocker

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:06:02 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 05/19/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 05/19/2015 04:25:01 PM
Date Inspection Closed by Inspector: 05/19/2015 04:17:42 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/19/2015	Installed bolt or bolts	05/19/2015		installed bolts in interlocker

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.16	2767 SIDE	01 -105	SIMN TO SIDING	
Walked/Operated	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.51	2766 CROS	77 -023	CROSSOVER 023-042	RBM Standard Point
Walked/Operated	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.55	2766 YARD	01 -049	NEW TRANSFER TO LITTLE ROCK	Spring-All Rail Extd length

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:06:12 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/20/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 05/20/2015 01:42:09 PM
Date Inspection Closed by Inspector: 05/20/2015 01:38:52 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2765 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

- NONE -

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)

[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:06:22 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 05/21/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 05/21/2015 03:07:58 PM
Date Inspection Closed by Inspector: 05/21/2015 02:58:45 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 061	417.75	418.60	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 061	418.60	418.77	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 022	418.58	418.60	No	BOKENKAMP	PASLAY	#22 W. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 042	418.60	419.05	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 042	417.84	418.60	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK

Track Traversed Information	
- NONE -	
Comments	

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.43	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.47	2766 CROS	77 -023	CROSSOVER 023-#1 MAIN	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.58	2766 CROS	77 -022	CROSSOVER 022	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 042	418.98	2767 YARD	01 -044	WE 044	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.12	2779 INDU	02 -748	SIDING TO KERMAGIE LEAD	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.14	2767 CNRT	01 -600	OLD TRANSFER OFF LITTLE ROCK	Spring-All Rail Extd length
Walked/Operated	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	418.77	2766 YARD	01 -061	WE 061	Solid Mang. Self Guarding
Walked/Operated	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.05	2767 YARD	01 -042	WE 042	

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:06:34 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/22/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 05/22/2015 01:54:06 PM
Date Inspection Closed by Inspector: 05/22/2015 01:48:16 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN	419.65	Difference in Cross : 0.5	103D-103.D - Fouled or insuffi	Scheduled for Repair	05/22/2015	Corr from Trk Mtce Plan	06/24/2015		

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:06:45 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 05/26/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 05/26/2015 02:48:18 PM
Date Inspection Closed by Inspector: 05/26/2015 02:47:12 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/26/2015	Installed bolt or bolts	05/26/2015		replaced interlocker bolts

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:06:54 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/28/2015	Inspected By: Printice Allen
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 05/28/2015 05:50:33 PM
Date Inspection Closed by Inspector: 05/28/2015 05:41:06 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK
Track Traversed Information										
- NONE -										
Comments										

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT 01 600	419.10		127A2-127.A2 - Insufficient fas	Scheduled for Repair	05/28/2015	Corr from Trk Mtce Plan	06/29/2015		need to plg and spike ties to secure movement
PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT 01 600	419.13	Gage Measurement : 58.5	53B3-53.B3 - Gage dimension on	Repaired Before Traffic	05/28/2015	Gaged track	05/28/2015		gauged 4 ties at a joint

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:07:04 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 05/29/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 05/29/2015 01:20:50 PM
Date Inspection Closed by Inspector: 05/29/2015 01:15:28 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10	Number of Bolts : 0	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/29/2015	Installed bolt or bolts	05/29/2015		put bolts in interlocker

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)