



**Photo 1 – View of the right-wing lift strut damage (photo courtesy of the pilot)**