



Photo 1 – View of rudder damage (photo courtesy of the FAA)



Photo 2 - View of empennage damage (photo courtesy of the FAA)