



Photo 1 – View of right wing damage (photo courtesy of Velocity Air Inc.)



Photo 2 - View of engine mount damage (photo courtesy of photo courtesy of Velocity Air Inc.)