

WPR20CA140 Picture



Figure 1: Dent in the tail boom.