



At 1500, the weather conditions reported at Harnett Regional Jetport Airport (HRJ), Erwin, North Carolina, 10 miles south of the accident site were, visibility 10 miles, clear skies, wind 240° at 6 knots, temperature 24°C (75F), dew point 2°C (35F), and barometric pressure of 29.91 inches of mercury.