

**Demko (Andrews) Jill**

---

**From:** Quentin Cook -  
**Sent:** Wednesday, April 11, 2012 8:16 PM  
**To:** Demko (Andrews) Jill  
**Subject:** N548SF maintenance records  
**Attachments:** Jose Wejebe.jpg

Hi Jill

This is the last work on record that was done on Mr. Jose Wejebe's plane. It had internal and external corrosion from standing outside at sea level. It was checked and repaired on 09/07/2010.

Regards

Quentin Cokinogenis

-----  
-----  
-----  
-

**From:** - - - - - ill - - - - -  
**To:** - - - - -  
**Cc:** Demko (Andrews) Jill <- - - - ->  
**Sent:** Wednesday, April 11- - - - -  
**Subject:** N548SF maintenance records

John,

I understand your facility did the last annual on the engine. Do you have any maintenance records you can send me for the airplane? We have not been able to locate the logbooks to date.

Thanks!

Jill Demko  
Air Safety Investigator  
National Transportation Safety Board

-----  
-----  
-----  
-----  
-

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.



Turbine Power Technologies



# Invoice

Date	Invoice #
9/7/2010	38

Bill To
Jose Wejebe

Ship To
Jose Wejebe

Web Site	Rep	Terms	Ship	Via
turbinepowertech.com	QC	Due on receipt	9/7/2010	Pick Up

Quantity	Item Code	Description	U/M	Price Each	Amount
1	Service	Repair for S/N: 872034 Tail Number: N548SF Repair 7 stator blocks on outer combustion chamber Repair 4 cracks on stator nozzle Exchange Oil Filter Service Ignitor Boxes Replace seal and chip detector		2,600.00	2,600.00T
2	Torch Replacement	Standard Charge for changing out torches new or refinished	ea	75.00	150.00T
2	205 Oil Supply Gasket	Oil Supply Gaskets	ea	12.50	25.00T
34	5mm Lockwasher	5mm Lock washers	ea	0.75	25.50T
2	87554887	62204-2RS1 SKF BEARING QIA	ea	33.00	66.00T
9	Aeroshell 500	24 Qts / 1 Case of Aeroshell 500 Oil	ea	9.17	82.53T
2	OS 20x38x7 TC	Replace 2 starter generator seals	ea	14.50	29.00T
8	Cup Washers	Cup Washer for Combustion Turbine Wheel	ea	4.00	32.00T
60	EC Bolts and Nuts	Engine Casing bolts and nuts	ea	2.00	120.00T
		Sales Tax		6.50%	203.45

Please Make Check Payable to Turbine Power Technologies, Inc.

**Total**

USD 3,333.48