## NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Washington, D.C. 20594 May 19, 2017

Errata 1 to Group Chairman's Factual Report

# **OPERATIONAL FACTORS**

#### **DCA15FA185**

Errata to Factual Report dated October 25, 2016

### A. ACCIDENT

Operator: British Airways (BA)
Location: Las Vegas, Nevada
Date: September 8, 2015

Time: 1613 Pacific Daylight Time

Airplane: Boeing 777-236ER (British registration G-VIIO)

### **ERRATA**

## E. FACTUAL INFORMATION; section 1.0, page 7

The second paragraph of the page has footnote 11 which states:

"Investigators found the right engine fire switch in the "down" (not activated) position. For further information, see Systems Group Chairman's Factual Report."

Footnote 11, should be replaced with the following:

"Investigators found the right engine fire switch in the "down" (not activated) position. For further information, see **Airworthiness** Group Chairman's Factual Report."

The fourth paragraph of the page and the last paragraph of the section states:

"During the evacuation at least 2 of the cabin crew received minor and serious injuries."

Should be replaced with the following:

"During the evacuation one cabin crewmember received a serious injury."

Submitted by,

Shawn Etcher Group Chairman Operational Factors