	TIME	DATE	
	5:40 PM	12/01/2014	
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION		ROUTING	
James Oliver, a 1st responder with Cooper Co. Fire Protection Di	lstrict	SYMBOL	INITIALS
Hangar 308 at Jesse Viertel Memorial Airport (KVER), Boonville,	МО		
also present: Todd Fox with NTSB and Chris Lang with Continental Motors			
statement prepared by Inspector Davis of the MCI FSDO			
CEN15FA060 - Accident investigation involving N6629V			
Mr. James Oliver is a volunteer firefighter with Cooper Co. Fire Protection District, and			
was a first responder to the subject airplane accident scene. He was contacted at his			
place of work and asked to meet with investigators at the hangar where the wreckage was			
transported for detailed investigation.			
		<u></u>	
Upon arrival, Mr. Oliver stated that he had turned the fuel selector to the "OFF" position,			
turned the mag switches off and removed the key, placing it on the ledge of the side panel.			
He also disconnected the battery because he thought a fuel pump was running. (NOTE: it was			
the hydraulic pump running that Mr. Oliver heard, due to a break in the landing gear supply			
lines; the auxilliary fuel pump switch was noted "off" during post-crash inspection).			
Mr. Oliver was asked where the fuel selector was positioned before he moved it, and he			
responded that he was certain it was in "AUX" position.			
	· ,		
CONCLUSION ACTION TAKEN, OR REQUIRED Accident investigation continuing. Mr. Oliver may be contacted through the CCFPD,			
DATE TITLE SIGNATURE			
12/05/2014 Aviation Safety Inspector FAA Form 1360-33 (10/12) Supersedes Previous Edition			Page 1