NTSB FORM 6120.15 (Rev. Nov-04)

NATIONAL TRANSPORTATION SAFETY BOARD RELEASE OF WRECKAGE

ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
DCA00MA026

REGISTRATION NUMBER N8079U Douglas DOUGL Bancho Cordova, CA The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to: OWNER OR OWNER'S REPRESENTATIVE – ADDRESS PARTS, PIECES, OR COMPONENTS BEING RETURNED: - R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. - R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative. SIGNATURE OF NTSB REPRESENTATIVE DATE	RELEASE OF WRECKAGE			DCA00MA026		
DOUGLAS DATE OF ACCIDENT/INCIDENT February 16, 2000 Rancho Cordova, CA The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to: OWNER OR OWNER'S REPRESENTATIVE - ADDRESS PARTS, PIECES, OR COMPONENTS BEING RETURNED: - R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. - R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.	PART II - RELEASE OF PARTS					
DATE OF ACCIDENT/INCIDENT February 16, 2000 Rancho Cordova, CA The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to: OWNER OR OWNER'S REPRESENTATIVE — ADDRESS PARTS, PIECES, OR COMPONENTS BEING RETURNED: R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.	REGISTRATION NUMBER		MAKE	MODEL		
Rancho Cordova, CA The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to: OWNER OR OWNER'S REPRESENTATIVE - ADDRESS PARTS, PIECES, OR COMPONENTS BEING RETURNED: R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.	N8079U		Douglas	DC-8		
The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components lieted below. When the examination is complete, they will be returned to: OWNER OR OWNER'S REPRESENTATIVE - ADDRESS PARTS, PIECES, OR COMPONENTS BEING RETURNED: R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.	DATE OF ACCIDENT/INCIDENT	LOCATION				
PARTS, PIECES, OR COMPONENTS BEING RETURNED: - R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. - R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.	February 16, 2000	Rancho	Cordova, CA			
PARTS, PIECES, OR COMPONENTS BEING RETURNED: - R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. - R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative. SIGNATURE OF NTSB REPRESENTATIVE TITLE DATE						
PARTS, PIECES, OR COMPONENTS BEING RETURNED: - R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed. - R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.	OWNER OR OWNER'S REPRESENTATIVE -					
- R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.	ADDRESS					
- R/H Elevator Control Tab push rod, with remaining Tab Crank Assembly attached at the forward rod end with bolt, nut, and cotter pin installed R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative.						
forward rod end with bolt, nut, and cotter pin installed. - R/H Elevator Control Tab Crank fitting, attached to the Control Tab (inboard) Hinge fitting. All wreckage from N8079U has hereby been released by the NTSB to the airplane owner's representative. SIGNATURE OF NTSB REPRESENTATIVE DATE	PARTS, PIECES, OR COMPONENTS BEING RETURNED:					
representative. SIGNATURE OF NTSB REPRESENTATIVE TITLE DATE	forward rod end with bolt, nut, and cotter pin installed.					
representative. SIGNATURE OF NTSB REPRESENTATIVE TITLE DATE				· · · · · · · · · · · · · · · · · · ·		
SIGNATURE OF NTSB REPRESENTATIVE TITLE DATE						
	representative.					
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	SIGNATURE OF NTSB REPRESENTATIVE	annes endelme de meder blosser en a 1900 e		DATE		
Frank Hilldrup Investigator-in-Charge 11/3/2004	Frank Hilldrup		Investigator-in-Charge	1944/2004 11/3/2004		

The registered owner or owner's representative will acknowledge	e receipt of the materials by signing this form	in the spaces designated below.
SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE	TITLE	DATE
ADDRESS	Representative	11/9/2004
Canton, MI 43188		





Search Col Package/EnvelopeServices Office / Print Services Freight Services Expedited Services Ship Track Manage My Account International Tools

Track Shipments Summary Results Printable Version Quick Help

You can also track:

- FedEx Trade Networks shipments
- By Email Track
- By FedEx Wireless Solutions

Single piece shipments

Tracking number

Status (1.13)

Date/Time

Destination sale

Service and

845454727004

Delivered

Nov 8, 2004 11:08 AM

ROCKLIN, CA

FedEx Express

845454726990

Delivered

Nov 8, 2004 11:08 AM

ROCKLIN, CA

FedEx Express

Wrong Address?

Reduce future mistakes by using

FedEx Address Checker.

Track more shipments

Shipping Freight? FedEx has LTL, air freight, surface and air expedited freight, multi piece package deliveries, and ocean freight.

Global Home | Service Info | About FedEx | Investor Relations | Careers | fedex.com Terms of Use | Privacy Policy

This site is protected by copyright and trademark laws under US and International law. All rights reserved. © 1995-2004 FedEx