

Tanl	c Car D	Car In	itials & CBTX 742045		
Tar	nk Car C	haracteristics/Feat	ures	Materia	
Type of Car:	Mon-pre	ssure Pressure DCn	yogenic Other_		
Specification N	o: DOT V	11 S 100 W1 Tank Test	pressure:	Tan	k Capacity: 3/800
Build Date:	9-2012	. Underframe:	Continuous 🗹	Stub S	Sill
Jacketed: Y	IN The	ermal Protection: Jack	keted T Sprayed	-on	Insulated: Y
Construction M	laterial: Ty	oe/Grade	Thickness		Stress: TMCON
	Fittings L	Damage	Jacket, Ta	ank a	nd Head Damage
Type fitting	Damaged?	Description Damage/Leak	Indicate location and s gouges, wheel burns, the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on
☐ Liquid Valve	☑ M. □ Leaking	3"			
☐ Vapor/ Air Valve	☑ M □ Leaking	ヹ			
Bottom Outlet Type:	Y € Leaking	12 J			
Pressure Relief Device Type:	Y N □ Leaking				
☐ Vacuum Relief Valve	Y M □ Leaking				
Gauging Device Type:	Y N □ Leaking				
☐ Manway Cover Plate	① M □ Leaking				
☐ Fill Hole	☑ Leaking				
☐ Sample Line	Y N Leaking				H
☐ Thermo- meter Well	Y N □ Leaking				
☐ Washout	Y N □ Leaking			\	
□ Sump	Y N □ Leaking				
☐ Other Type:	Y N Leaking	v.		/ .	

0934. F



Tank Car Damage Assessment				Car Initials & CTCX 735779		
Tai	nk Car C	haracteristics/Feat	tures	Materia	al	
Type of Car:	⊠ Non-pre	essure Pressure Cr	yogenic Other_			
Specification N			pressure:		ak Capacity: 30100	
Build Date:	2-2017	Underframe:	☐ Continuous ➤	Stub S	Sill	
Jacketed: Y	W The	ermal Protection: Jac	keted T Sprayed	l-on	Insulated: Y N	
Construction M	laterial: Ty	pe/Grade	. Thickness		Stress: TMCON	
	Fittings L	Damage	Jacket, T	ank a	nd Head Damage	
Type fitting	Damaged?	Description Damage/Leak	Indicate location and gouges, wheel burns, the appropriate diagra	dents, ra	f damage (punctures, cracks, scores, il burns, underframe, and leaks) on	
⊠ Liquid Valve	Y M □ Leaking	3/1			-1	
☐ Vapor/ Air Valve	▼ ☑ □ Leaking	7,,				
Digital Bottom Outlet Type:	Y Mi □ Leaking	SHEARED				
☐ Pressure Relief Device Type:	Y N □ Leaking					
☐ Vacuum Relief Valve	Y N □ Leaking					
Gauging Device Type:	Y N Leaking					
☐ Manway Cover Plate	Y N Leaking			(
☐ Fill Hole	Y N Leaking				<i>U</i> '	
☐ Sample Line	Y N □ Leaking				TH	
☐ Thermo- meter Well	Y N □ Leaking					
☐ Washout	Y N Leaking			\		
□ Sump	Y N □ Leaking					
☐ Other Type:	Y N □ Leaking					


2533856



5/1/14

Tank Car Damage Assessment				Car Initials & CTCX 7430		
Tar	nk Car C	haracteristics/Feat	ures	Materia	al	
Type of Car:	⊠ Non-pre	ssure Pressure DCn	ogenic Other_			
Specification N	o: DOT	115100W Tank Test	pressure:	Tan	k Capacity: 31790	
Build Date: 0	5-20.12	Underframe: [Continuous E	Stub S	Sill	
Jacketed: Y	N The	ermal Protection: Jack	keted T Sprayed	l-on	Insulated: Y N	
Construction M	laterial: Typ	oe/Grade	Thickness		Stress: TMCON	
	Fittings L	Damage	Jacket, T	ank a	nd Head Damage	
Type fitting	Damaged?	Description Damage/Leak	Indicate location and a gouges, wheel burns, the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on	
包 Liquid Valve	☑ -Æ	3"				
	☑ DE Leaking	λ'				
Bottom Outlet Type:	Y De Leaking	Charles In the Control of the Contro				
Pressure Relief Device Type:	Y ⊠ □ Leaking					
☐ Vacuum Relief Valve	Y N □ Leaking					
☐ Gauging Device Type:	Y N Leaking					
☐ Manway Cover Plate	T N □ Leaking			(
☐ Fill Hole	Y M Leaking	e e e e e e e e e e e e e e e e e e e				
☐ Sample Line	Y M □ Leaking				H	
☐ Thermo- meter Well	Y N Leaking					
☐ Washout	Y M □ Leaking			\		
□ Sump	Y N Leaking					
☐ Other Type:	Y N C Leaking	*				


1005 HES. 3. F.



5/1/14

Tanl	Car D	amage Assess			
Tar	k Car Ci	haracteristics/Feat	ures	Materia	al Control of the Con
Type of Car:	Ø Non-pre	ssure Pressure Cry	ogenic Other_		
Specification N	DOT II	I A 100W (Tank Test	pressure:	Tan	k Capacity: 30090
Build Date: 🔿			Continuous Z	Stub S	ill
Jacketed: Y	M The	ermal Protection: Jack	keted T Sprayed	-on	Insulated: Y N
Construction M	laterial: Ty	pe/Grade	Thickness		Stress: TMCON
	Fittings L	Damage	Jacket, Ta	ank a	nd Head Damage
Type fitting	Damaged?	Description Damage/Leak		dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on
☑ Liquid Valve	☑ Leaking	31'		Г	
Vapor/ Air Valve	Y ⊸N □ Leaking	ん'			
Ø Bottom Outlet Type:	Y ₩ Leaking	TORN OFF			
☐ Pressure Relief Device Type:	Y N □ Leaking				
☐ Vacuum Relief Valve	Y N Leaking				
☐ Gauging Device Type:	Y N Leaking				
☐ Manway Cover Plate	Y N Leaking			(
☐ Fill Hole	Y N Leaking				· .
☐ Sample Line	Y M □ Leaking				H
☐ Thermo- meter Well	Y N □ Leaking				
☐ Washout	Y N □ Leaking			\	
□ Sump	Y N Leaking				
Other Type:	Y N D Leaking				

1025 HOS 20.10F




CTCX 735774

5/1/14

Tank Car Damage Assessment					Car Initials & Number CBTX 741925		
Tar		haracteristics/Feat		Materia			
Type of Car:	⊠Non-pre	ssure Pressure DCr	yogenic Other_				
Specification N	o. Dotill	S 100W (Tank Test	pressure:	Tan	k Capacity: 31870		
Build Date:	9-2012:	Underframe:	☐ Continuous 万	₹ Stub S	Sill		
Jacketed: Y	N The	ermal Protection: Jac	keted T Sprayed	l-on	Insulated: Y N		
Construction N	laterial: Ty	oe/Grade	. Thickness		Stress: TMCON		
	Fittings L	Damage	Jacket, T	ank al	nd Head Damage		
Type fitting	Damaged?	Description Damage/Leak	Indicate location and a gouges, wheel burns, the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on		
∐ Liquid Valve	☑ Leaking	3"					
☑ Vapor/ Air Valve	Y N Leaking	l'			•		
Bottom Outlet Type:	☑ ⑤ Leaking	TPG A					
☑ Pressure Relief Device Type:	Y № □ Leaking	ABSONBENTS PADS IN PLACE					
☐ Vacuum Relief Valve	Y N Leaking						
Gauging Device Type:	Y N Leaking						
☐ Manway Cover Plate	Y N □ Leaking			(
☐ Fill Hole	Y N Leaking				<i>U</i> •		
☐ Sample Line	T M □ Leaking				TH		
☐ Thermo- meter Well	Y N □ Leaking						
☐ Washout	Y N □ Leaking						
□ Sump	Y N □ Leaking						
☐ Other Type:	Y N Leaking			/			


1017 No. 3 Sex



☐ Leaking

Type: _


1054 HPS. F. S. F.



5/11/

Tank	Car D	amage Assess	Sment Car Initials & Number CBTX 7417		
Tan	k Car C	haracteristics/Feat	ures	Materia	
Type of Car:	□ Non-pre	ssure Pressure Cry	ogenic Other		
Specification N	o: DOT IH	S 100 W Tank Test	pressure:	Tan	k Capacity: 3 800
Build Date:	7-2012	Underframe:	Continuous &	Stub S	Sill
Jacketed: Y	M. The	ermal Protection: J Jack	keted T Sprayed	d-on	Insulated: Y N
Construction M	laterial: Ty	oe/Grade	Thickness		Stress: TMCON
	Fittings L	Damage	Jacket, 7	ank a	nd Head Damage
Type fitting	Damaged?	Description Damage/Leak	Indicate location and gouges, wheel burns the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on
전 Liquid Valve	Y ï □ Leaking	23/			
	☑ Leaking	べ			
Bottom Outlet Type:	Y ₩ □ Leaking	13 d.			
Pressure Relief Device Type:	Y 個 □ Leaking				
☐ Vacuum Relief Valve	Y N Leaking				
Gauging Device Type:	Y N Leaking				
☐ Manway Cover Plate	Y N Leaking				
☐ Fill Hole	Y M □ Leaking				
☐ Sample Line	Y N Leaking	9 4			TA
☐ Thermo- meter Well	Y N D Leaking				
☐ Washout	Y N Leaking				
□ Sump	Y N U Leaking				
☐ Other Type:	Y N Leaking		(3)		


11085 7087



5/1/14

Tanl	c Car D	amage Assess	ment Car Initials & CBTX 74184		
Tar	nk Car C	haracteristics/Feat	ures	Materia	al
Type of Car:	⊠ Non-pre	ssure Pressure Cry	ogenic Other_		
Specification N	o: DOT 11	15 100 w \ Tank Test	pressure:	Tan	ik Capacity: 31870
Build Date: 6	3-2012	Underframe:	Continuous 2	Stub S	Sill
Jacketed: Y	IN The	ermal Protection: Jack	keted T Sprayed	l-on	Insulated: Y N
Construction N	laterial: Ty	oe/Grade	Thickness		Stress: TMCON
	Fittings L	Damage	Jacket, T	ank a	nd Head Damage
Type fitting	Damaged?	Description Damage/Leak	Indicate location and : gouges, wheel burns, the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on
点 Liquid Valve	Y M □ Leaking	3"			
√apor/ Air Valve	☑ — ☑ □ Leaking	√'			
Bottom Outlet Type:	Y do la Leaking	To January Control of the Control of			
Pressure Relief Device Type:	Y M Leaking				
☐ Vacuum Relief Valve	Y N Leaking				
Gauging Device Type:	Y N Leaking				
☐ Manway Cover Plate	Y N Leaking				
☐ Fill Hole	Y N □ Leaking				
☐ Sample Line	Y M □ Leaking				H
☐ Thermo- meter Well	Y N Leaking	9			
☐ Washout	Y N Leaking			\	
□ Sump	Y N Leaking				
☐ Other Type:	Y N Leaking				

1581 5 REST




5/2/14

Tanl	amage Assess	Sment Car Initials & CBTX741712			
Tar	k Car C	haracteristics/Feat	ures	Materia	
Type of Car:	⊠ Non-pre	ssure Pressure Cry	ogenic Other_		
Specification N	o: 1118	10000 Tank Test	pressure:	Tan	k Capacity: 31870
Build Date:	105-50	2 Underframe: [Continuous &	Stub S	Sill
Jacketed: Y	N The	ermal Protection: Jack	keted T Sprayed	l-on	Insulated: Y N
Construction M	laterial: Ty _l	oe/Grade	Thickness		Stress: TMCON
	Fittings L	Damage	Jacket, T	ank a	nd Head Damage
Type fitting	Damaged?	Description Damage/Leak	Indicate location and gouges, wheel burns, the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on
☑ Liquid Valve	Y M □ Leaking	3"	\		
X Vapor/ Air Valve	☑ M Leaking	て"			
Bottom Outlet Type:	Y M □ Leaking	SHEARES BAL CLOSED.			
☐ Pressure Relief Device Type:	Y N □ Leaking			1	
☐ Vacuum Relief Valve	Y N □ Leaking			\	
☐ Gauging Device Type:	Y N □ Leaking				
☐ Manway Cover Plate	Y N Leaking			(
☐ Fill Hole	Y N Leaking			-	\ .
☐ Sample Line	Y M □ Leaking				H
☐ Thermo- meter Well	Y N Leaking				
☐ Washout	Y N □ Leaking				
Sump	Y N □ Leaking				
☐ Other Type:	Y N Leaking	*			

CBIX 741712 A B LEFT - Side B RIGHT-SIDE TOP 12" x 55" x: 1/2. W. College A. A. BOTTOM

CBTX 7417:12





98"

National Transportation Safety Board Tank Car Damage Assessment Form

		4				
Reporting Marks	CBTX 7	41712	Car Location City/State			
Date inspected	Railr	oad	DOT Specification	DOTIII		
Last Contained	A John Wall		Was product released?	YES		
(Indicate One)	Jacket No		Does car contain product	NO		
Car builder	ARI	Stub Sill Design		Built Date	7-2012	
Capacity (GAL)			LD Limit (LB)			

Indicate number on figures below within damaged areas. (sketched in by inspector) Walt Right A-END Top Center Line dup 811 wide A 101" Right Center Line Pain dur OK A B Left Center Line



National Transportation Safety Board Tank Car Damage Assessment Form Half-height head shreld **B-Head** A-Head Station Stencil Qual. Due Tank Qual. **Thickness** Serv. Equip. PRD Lining Rule 88 Stub Sill Comments: ed shreld

TANK OR JACKET DAMAGE

1. Document estimated location of damage on Figures located on page 1 of this report and document dimensions coinciding with number below. (photos should be numbered and attached to coincide with numbers below)

1.	Affected?	Location?	Dimensions: Length Width Denth
-	Defect type?		S Contracting Depting
		Shape?	Possible Cause?
2	Affected?	Location?	Dimensions: Length Width Depth
-	Defect type?	Shape?	Possible Cause?
3	Affected?	Location?	Dimensions: Length Width Depth
-	Defect type?	Shape?	Possible Cause?
4	Affected?	Location?	Dimensions: Length Width Depth
-	Defect type?	Shape?	Possible Cause?
5	Affected?	Location?	Dimensions: Length Width Depth
-	Defect type?	Shape?	Possible Cause?
6	Affected?	Location?	Dimensions: Length Width Depth
-	Defect type?	Shape?	Possible Cause?
7	Affected?	Location?	Dimensions: Length Width Depth
-	Defect type?	Shape?	Possible Cause?
8	Affected?	Location?	D: : : : : : : : : : : : : : : : : : :
7	Defect type?	Shape?	Possible Cause? Width Depth

2.	Was	this	tank	car	exposed	to	fire?
----	-----	------	------	-----	---------	----	-------

- How long was the car exposed to fire?
- What percentage/locations of the tank were exposed to fire? 4.

Indicate location in figures on page 1.

- What material burned to create the fire that the car was exposed to? 5.
- To what degree did the car roll? Initially degrees and stopped at

7. Distance traveled from track center? B-end?	A-end?	Center?	and the market
--	--------	---------	----------------



orm			
orm		VALVE DAMAGE	
	TCAD-1.2 and supplement descrip	tion as indicative of damage belo TOP	w:
Vur	nber of damaged valves?	40.00 B 3.00 B 4.00 B 10 B 10 B 5.00 B 5.00 B 10 B	encil if other than qual. Decal
	-		
a	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
b	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
c	Type of damaged valve?	Manufacturer?	Cause?
	Gasket Type?	O-ring type?	Serial Number
d	Type of damaged valve?	Manufacturer?	Cause?
_	Gasket Type?	O-ring type?	Serial Number
e	Type of damaged valve?	Manufacturer?	Cause?
	Gasket Type?	O-ring type?	Serial Number
Sket	tch in dome or dual housing arrange	ement information in relation to	valve location in provided figure.
Lett	ering should coincide with lettering	above, along with any attached p	oictures.
			A-End

a	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
b	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
c	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
d	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
e	Type of damaged valve?	Manufacturer?	Cause?
	Gasket Type?	O-ring type?	Serial Number

Other information or description deemed pertinent by inspector:




STATE TO A


Inspector's Name dent glant burnt of 26 00 0 Paint OK 23" 1/2 erack toweld Deflection 1/2 1311W-1811n Page 4 of 4


Tanl	amage Assess	Sment Car Initials & CRTV-7417 20			
Tar	nk Car Cl	haracteristics/Feat	ures	Materia	
Type of Car:	Non-pre	ssure Pressure Cry	ogenic Other_		
Specification N	o: \\\	Stoom Tank Test	pressure:	Tan	k Capacity: 3 870
Build Date:	7-2012	Underframe:	Continuous	Stub S	Sill
Jacketed: Y	N The	ermal Protection: J Jack	keted T Sprayed	-on	Insulated: Y N
Construction M	laterial: Typ	oe/Grade	Thickness		Stress: TMCON
	Fittings L	Damage			nd Head Damage
Type fitting	Damaged?	Description Damage/Leak	Indicate location and s gouges, wheel burns, the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on
☑ Liquid Valve	Y M □ Leaking	3/1			
⊠ Vapor/ Air Valve	☑ M □ Leaking	2"			
図 Bottom Outlet Type:	Y € Leaking	intact			
☐ Pressure Relief Device Type:	Y N □ Leaking			7	
☐ Vacuum Relief Valve	Y N Leaking				
Gauging Device Type:	Y N □ Leaking				
☐ Manway Cover Plate	Y N Leaking			(
☐ Fill Hole	Y M Leaking				
☐ Sample Line	Y M □ Leaking				H
☐ Thermo- meter Well	Y N □ Leaking				
☐ Washout	Y N □ Leaking			\	
□ Sump	Y N □ Leaking				
☐ Other Type:	Y N Leaking		101	/	

210 B 85.20 F

CBTY 741720







1		1	
	Z)
1	-		/

	Reporting Marks	CBTX 7417	20	Car Location City/State	4	
	Date inspected	Railro	oad	DOT Specification	DOTILISI	10001
	Last Contained			Was product released?	NO	
のできる	(Indicate One)	Jacket		Does car contain product	Yes	
	Car builder	ARI	Stub Sill Design		Built Date	7-2012
	Capacity (GAL)	31820		LD Limit (LB)	Ŋ	

Indicate number on figures below within damaged areas. (sketched in by inspector) A-END Top Center Line - Oil mark 11 dep 300 deep 47.85 Left Center Line



Park care land of her box	N.	And his			
		Station Stencil	Qual.	Due	
Mu Mu	Tank Qual.				
The state of the s	Thickness			1420	
	Serv. Equip.				
	PRD	CAME			
9					
\mathbb{C}^n	Lining				
/6 \	Rule 88				
	Stub Sill				
Comments: And Forn head	yd M				

TANK OR JACKET DAMAGE

1. Document estimated location of damage on Figures located on page 1 of this report and document dimensions coinciding with number below. (photos should be numbered and attached to coincide with numbers below)

	merang with number below	(photos should be mulli	bered wild attached to comerate with hambers	
1.	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	THE P
2	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	
3	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	•
4	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	
5	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	
6	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	
7	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	
8	Affected?	Location?	Dimensions: Length Width	Depth
-	Defect type?	Shape?	Possible Cause?	
100		A designation of the second se	A CONTRACTOR OF THE PROPERTY O	Market and the second state of the second stat

- 2. Was this tank car exposed to fire?
- 3. How long was the car exposed to fire?
- 4. What percentage/locations of the tank were exposed to fire? Indicate location in figures on page 1.
- 5. What material burned to create the fire that the car was exposed to?
- 6. To what degree did the car roll? Initially degrees and stopped at
- 7. Distance traveled from track center? B-end? ______A-end? _____Center? _____



8.	Brief description	of details of	of surfaces t	tank was exposed	after derailment?	E.g. mud,	track, rocks, etc

VALVE DAMAGE

Utilize Form TCAD-1.2 and supplement description as indicative of damage below:

TOP

1. Number of damaged valves?

Document station stencil if other than qual. Decal

a	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
b	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
c	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
d	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
e	Type of damaged valve?	Manufacturer?	Cause?
X.	Gasket Type?	O-ring type?	Serial Number

Sketch in dome or dual housing arrangement information in relation to valve location in provided figure. Valve Lettering should coincide with lettering above, along with any attached pictures.

A-End

воттом


2. Description of damage? Valve, Coils etc..._____Document station stencil if other than qual. Decal____

a	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
b	Type of damaged valve?	Manufacturer?	Cause?
-	Gasket Type?	O-ring type?	Serial Number
c	Type of damaged valve?	Manufacturer?	Cause?
2	Gasket Type?	O-ring type?	Serial Number
d	Type of damaged valve?	Manufacturer?	Cause?
1	Gasket Type?	O-ring type?	Serial Number
e	Type of damaged valve?	Manufacturer?	Cause?
	Gasket Type?	O-ring type?	Serial Number

Other information or description deemed pertinent by inspector:




Inspector's Name



Tanl	Car D	amage Assess	sment Car Initials & Number CBTX 741672				
Tank Car Characteristics/Features Material							
Type of Car: ☐ Non-pressure ☐ Pressure ☐ Cryogenic ☐ Other							
Specification N	. 1115100	Tank Test	pressure:	Tan	k Capacity: 3/9/0		
Build Date: 07	- 2012	Underframe:	☐ Continuous 区	Stub S	Sill		
Jacketed: Y	N The	ermal Protection: Jack	keted T Sprayed	-on	Insulated: Y N		
Construction M	laterial: Ty	oe/Grade	Thickness		Stress: TMCON		
	Fittings L	Damage	Jacket, Ta	ank a	nd Head Damage		
Type fitting	Damaged?	Description Damage/Leak	Indicate location and s gouges, wheel burns, the appropriate diagra	dents, ra	damage (punctures, cracks, scores, il burns, underframe, and leaks) on		
Liquid Valve	Y M □ Leaking	3"					
\(\text{\infty}\) Vapor/ Air Valve	☑ R □ Leaking	, (I					
D Bottom Outlet Type:	Y M	value and handle are infact					
☐ Pressure Relief Device Type:	Y N □ Leaking						
☐ Vacuum Relief Valve	Y N □ Leaking						
☐ Gauging Device Type:	Y N □ Leaking						
☐ Manway Cover Plate	Y N □ Leaking			(
☐ Fill Hole	Y N □ Leaking				<i>U</i> *		
☐ Sample Line	Y N □ Leaking				H		
☐ Thermo- meter Well	Y N □ Leaking						
☐ Washout	Y N □ Leaking						
☐ Sump	Y N □ Leaking						
☐ Other Type:	Y N □ Leaking			/			


1.465.

1433 11 pst 77.2°F



			_	Car Ini	tiple ?			
Tanl	Car D	amage Assess		Numbe	er 743025			
Tar	Tank Car Characteristics/Features							
Type of Car:	Type of Car: ☑ Non-pressure ☐ Pressure ☐ Cryogenic ☐ Other							
Specification N	DOT IL	5 100wl Tank Test	pressure:	Tan	k Capacity: 31830			
Build Date:	5-201	Underframe:	Continuous 🔀	Stub S	ill			
Jacketed: Y	The The	ermal Protection: Jack	ceted T Sprayed	-оп	Insulated: Y N			
Construction M	laterial: Typ	oe/Grade	Thickness		Stress: TMCON			
	Fittings L	Damage	Jacket, Ta	ank ai	nd Head Damage			
Type fitting	Damaged?	Description Damage/Leak	Indicate location and s gouges, wheel burns, the appropriate diagra	dents, rai	damage (punctures, cracks, scores, il burns, underframe, and leaks) on			
☑ Liquid Valve	Y Mi □ Leaking	3"	•					
∕d Vapor/ Air Valve	☑ M □ Leaking	1"						
Bottom Outlet Type:	Y € Leaking	SHEARED						
☐ Pressure Relief Device Type:	Y N □ Leaking							
☐ Vacuum Relief Valve	Y N □ Leaking	a a						
Gauging Device Type:	Y N Leaking							
☐ Manway Cover Plate	Y N Leaking							
☐ Fill Hole	Y M □ Leaking				. · ·			
☐ Sample Line	Y N □ Leaking				H			
☐ Thermo- meter Well	Y N □ Leaking							
☐ Washout	Y N □ Leaking							
☐ Sump	Y N Leaking							
☐ Other Type:	Y N Leaking							


824 4P55. F.



5/3/14

Tank Car Damage Assessment				Car Initials & Number CBTX 743190	
Tar	nk Car C	haracteristics/Feat	ures	Materia	3
Type of Car:					
Specification N	00w Tank Test	pressure: Tank Capacity: 31830			
Build Date: 04-2013 Underframe: Continuous Stub Sill					
Jacketed: Y N Thermal Protection: J Jacketed T Sprayed-on Insulated: Y N					
Construction Material: Type/Grade Thickness Stress: T M C O N					Stress: TMCON
	Fittings L	Damage	Jacket, Tank and Head Damage		
Type fitting Damaged? Description Damage/Leak			Indicate location and severity of damage (punctures, cracks, scores, gouges, wheel burns, dents, rail burns, underframe, and leaks) on the appropriate diagram(s).		
⊠ Liquid Valve	☑ M □ Leaking	311			
Vapor/ Air Valve	Y M □ Leaking	211			
☐ Bottom Outlet Type:	Y ₩ □ Leaking	value and hadle intact			
☐ Pressure Relief Device Type:	Y N □ Leaking				
☐ Vacuum Relief Valve	Y N □ Leaking	a.			
☐ Gauging Device Type:	Y N Leaking				
☐ Manway Cover Plate	Y N Leaking				
☐ Fill Hole	Y M □ Leaking				
☐ Sample Line	Y M □ Leaking			1	H
☐ Thermo- meter Well	Y N Leaking	1			
☐ Washout	Y N □ Leaking				
☐ Sump	Y N Leaking				
☐ Other Type:	Y N Leaking			<i>)</i>	

1400 hrs 14 psi 85.4°F




CBTX 743190

5/3/M


Tank Car Damage Assessment				Car Ini	tials & CBTX 743/97		
Tank Car Characteristics/Features Material							
Type of Car: Non-pressure Pressure Cryogenic Other							
					oressure: Tank Capacity: 3 9 10		
Build Date: 04 - 1.013 Underframe: ☐ Continuous ☐ Stub Sill							
Jacketed: Y N Thermal Protection: J Jacketed T Sprayed-on Insulated: Y N							
Construction M	Construction Material: Type/Grade Thickness Stress: T M C O N						
I	Fittings E	Damage	Jacket, Tank and Head Damage				
Type fitting	Damaged?	Description Damage/Leak	Indicate location and severity of damage (punctures, cracks, scores, gouges, wheel burns, dents, rail burns, underframe, and leaks) on the appropriate diagram(s).				
☑ Liquid Valve	Y M □ Leaking	3/1					
☐ Vapor/ Air Valve	☑ M □ Leaking	Ju					
Bottom Outlet Type:	▼ Ø □ Leaking	intact		n			
☐ Pressure Relief Device Type:	Y N □ Leaking						
☐ Vacuum Relief Valve	Y N Leaking						
☐ Gauging Device Type:	Y M □ Leaking						
☐ Manway Cover Plate	y N □ Leaking		191	(
☐ Fill Hole	Y N □ Leaking			aginti estere aprova constituta il reco			
☐ Sample Line	Y N Leaking				H		
☐ Thermo- meter Well	Y N Leaking						
☐ Washout	Y M □ Leaking			\			
☐ Sump	Y N □ Leaking						
☐ Other Type:	Y N Leaking			/			

1325 hrs 74.7°F



Tank Car Damage Assessment				Car Initials & Number CBTX 7 43147	
Tan	haracteristics/Feat	ures	Materia		
Type of Car: Non-pressure Pressure Cryogenic Other					
Specification N	Tank Test	pressure: Tank Capacity: 3/8/20			
Build Date: 03-2013 Underframe: ☐ Continuous △ Stub Sill					Sill
Jacketed: Y N Thermal Protection: J Jacketed T Sprayed-on Insulated: Y N					
Construction M	laterial: Ty	oe/Grade	Thickness		Stress: TMCON
Fittings Damage			Jacket, Tank and Head Damage		
Type fitting	Damaged?	Description Damage/Leak	Indicate location and severity of damage (punctures, cracks, scores, gouges, wheel burns, dents, rail burns, underframe, and leaks) on the appropriate diagram(s).		
剤 Liquid Valve	☑ ÞÐ □ Leaking	311			
区 Vapor/ Air Valve	Y A □ Leaking	211			
Bottom Outlet Type:	Y 風 □ Leaking	intact			
Pressure Relief Device Type:	Y N □ Leaking				
☐ Vacuum Relief Valve	Y N Leaking	· · ·			
Gauging Device Type:	Y N □ Leaking	,			
☐ Manway Cover Plate	Y N Leaking			(
☐ Fill Hole	Y N Leaking				
☐ Sample Line	Y M □ Leaking				TH
☐ Thermo- meter Well	Y N Leaking				
☐ Washout	Y N □ Leaking			\	
□ Sump	Y N Leaking				
☐ Other Type:	Y N C Leaking				


1453 hrs 85.5°F 15 psc



5/3/14

Tank Car Damage Assessment				Car Initials & Number GATX 286291		
Tank Car Characteristics/Features Mater					al	
Type of Car: ☐ Non-pressure ☐ Pressure ☐ Cryogenic ☐ Other						
Specification N	o. not a	Tank Test	pressure: Tank Capacity: 31700			
Build Date: burnt of Sunderframe: Underframe: Continuous Stub Sill						
Jacketed: Y N Thermal Protection: J Jacketed T Sprayed-on Insulated: Y N						
Construction N	Construction Material: Type/Grade Thickness Stress: T M C O N					
	Fittings L	Damage	Jacket, Tank and Head Damage			
Type fitting Damaged? Description Damage/Leak			Indicate location and severity of damage (punctures, cracks, scores, gouges, wheel burns, dents, rail burns, underframe, and leaks) on the appropriate diagram(s).			
区 Liquid Valve	M M □ Leaking	3"				
☼ Vapor/ Air Valve	☑ Leaking	Σ''				
☐ Bottom Outlet Type:	Y N □ Leaking			-		
☐ Pressure Relief Device Type:	Y N Leaking					
☐ Vacuum Relief Valve	Y № □ Leaking	19	H			
☐ Gauging Device Type:	Y N Leaking					
☐ Manway Cover Plate	Y N Leaking					
☐ Fill Hole	Y M □ Leaking		Ų			
☐ Sample Line	Y M Leaking				H	
☐ Thermo- meter Well	Y N Leaking					
☐ Washout	Y N □ Leaking					
☐ Sump	Y N □ Leaking					
☐ Other Type:	Y N Leaking			<i>)</i> .		

1350 hrs. 8,4,4°F



GATX 286291

