

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-96-1 10/2/1996	Main Transmission Assy P/N 407-040-006-103 Oil Transfer Passage, Inspection of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-96-2 10/15/1996	407 Safety of Flight Ship Grounding	6/30/2009 0	Complied With	X			BHTI
ASB 407-96-3 10/21/1996	407 Engine FADEC Hardness, Replacement of, and FADEC Fault Annunciation, Interpretation of	6/30/2009 0	Complied With	X			BHTI
ASB 407-96-4 11/18/1996	Engine FADEC Electronic Control Unit, Inspection of	6/30/2009 0	Superseded by 407-97-09	X			BHTI
ASB 407-96-5 11/18/1996	Engine Overspeed Protection, Disabling of	6/30/2009 0	Superseded by 407-97-09	X			BHTI
ASB 407-97-6 12/3/1996	Engine Overspeed Protection Trip Limit, Increase of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-97-7 2/27/1997	Tail Rotor Drive, Shimming Procedure Bearing Support to Bearing Hangar, Introduction of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-97-8 7/3/1997	Allison 250-C47B Engine FADEC, New Configuration, Introduction of (Canadian TCA)	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-97-9 Rev A 10/3/1997	Allison 250-C47B Engine FADEC, New Configuration, Introduction of (FAA/DER) CEB A-73-6015	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-97-10 7/29/1997	Main Rotor Pitch Links Retaining Hardware, Replacement of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-97-11 8/29/1997	Swashplate Duplex Bearing P/N 406-310-402-103, Introduction of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-97-12 10/7/1997	Warning Horns: FADEC Fail, Engine Out, and Low Rotor RPM, Replacement of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-97-13 Rev A 2/18/1998	T/R Driveshaft, Disk Pack Couplings P/N 406-040-340-101, Torque Check and Special Inspection, Introduction of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-97-14 Rev C 12/4/2001	T/R Gearbox P/N 406-040-400-ALL, Torque Check and Installation Procedures, Modification of AMOC for AD 97-24-17 para (e)	6/30/2009 0	Complied With	X			BHTI
ASB 407-97-15 12/23/1997	Engine FADEC Electronic Control Unit, Replacement of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-96-16 1/30/1998	Cargo Hook Kit 206-706-341-109 /-111, Modification of	6/30/2009 0	Not Applicable by Kit Part Number	X			BHTI
ASB 407-97-17 Rev A 6/28/1998	Vertical Fin Inspection, P/N 206-020-113-221 /-229	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-98-18 5/27/1998	Door Latch Assy, Inspection of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-98-19 6/19/1998	Driveshaft, Engine to Transmission, Replacement of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-98-20 7/3/1998	Hydraulic Relief Valve, Replacement of P/N 206-076-036- 101	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-98-21 12/4/1998	Engine HMU Drivespline Inspection	6/30/2009 0	Repetitive Inspection 2500 hrs	X			BHTI
ASB 407-98-22 12/10/1998	Ch. 4 Airworthness Limitations Schedule	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-98-23 Rev A 10/25/2001	Oil Cooler Blower Bearing, Introduction of New P/N 407-340- 339-103 and Royco 13	6/30/2009 0	Cancelled and	X			BHTI
ASB 407-98-24 12/21/1998	Engine Fairing, RH Door Hinge, Modification of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-99-25 1/6/1999	Main Rotor Pitch Horn 407-010-103-101 and Attaching Hardware, One Time Inspection of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-99-26 Rev C 2/28/2002	Tailboom 407-030-801-101 /-105, Inspection of	6/30/2009 0	Complied With	X			BHTI
ASB 407-99-27 Rev A 6/9/1999	Vne Restoration to 130 KIAS, Introduction of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-99-28 4/28/1999	Engine FADEC ECU Software Upgrade	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-99-29 5/10/1999	Crew Seat Belt Assy, Replacement of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-99-30 5/10/1999	Door Latch Baseplate Assy, Replacement of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-99-31 9/10/1999	FADEC - Direct Reversion to Manual (DRTM) System, Upgrade to	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-99-32 REV A 3/20/2002	Horizontal Stabilizer Slats, 407-023-002-117, Replacement of	6/30/2009 0	Cancelled and Superseded by ASB 407-02-52	X			BHTI
ASB 407-99-33 Rev B 12/3/2000	Vne Restoration to 140 KIAS, Introduction of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-00-34 Rev A 5/31/2001	Rolls Royce Allison 250-C47B engine self-sealing magnetic chip detectors, Inspection of	6/30/2009 0	Rev. "A" Advise that Rolls Royce Has Issued a Cancellation Notice to CEB A-72-6032	X			BHTI
Asb 407-00-35 Rev A 11/12/2001	Hangar Bearings 406-040-339-ALL & 407-340-339-103 Inspection and Lubrication of	6/30/2009 0	Cancelled and Superseded by ASB 407-01-47 Rev A	X			BHTI
ASB 407-00-36 Rev A 1/14/2003	170 AMP Maximum Continuous Electrical Load Limit for Operations above 10,000' Density Altitude, Introduction of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-00-37 10/30/2000	Rolls Royce C47 Engine, Replacement of Compressor Scroll 23066737 and 23072848	6/30/2009 0	Complied With	X			BHTI
ASB 407-00-38 12/8/2000	Fuel Vent Line , Replacement of	6/30/2009 0	Complied With	X			BHTI
ASB 407-01-39 Rev A 5/30/2001	Bracket, 407-040-321-101/-103, Inspection of. (Helicopters with flywheel adapter installed)	6/30/2009 0	Not Applicable	X			BHTI
ASB 407-01-40 3/6/2001	Rescue Hoist, BL-16600 Series, Breeze Eastern Customer Alert Bulletin CAB-100-58	6/30/2009 0	Not Applicable	X			BHTI
ASB 407-01-41 5/23/2001	Fuel Filler Cap Assy - Shimming and Electrical Bonding Procedures, Introduction of	6/30/2009 0	Complied With	X			BHTI
ASB 407-01-42 4/5/2001	Aft Fuel Cell Fuel Feed Line, Inspection of / Aft fuel cell standpipe, Replacement of	6/30/2009 0	Complied With	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-01-43 6/8/2001	One Time Inspection of the Engine to Transmission shaft 206-340-300-105	6/30/2009 0	Complied With	X			BHTI
ASB 407-01-44 Rev D 7/19/2002	Oil Cooler Blower Hangar Bearing 407-340-339-103, Replacement of Supersedes ASB 407-98-23	6/30/2009 0	Cancelled and Superseded by ASB 407-04-63	X			BHTI
ASB 407-01-45 Rev A 11/21/2001	206-340-300-107 Engine to Transmission Shaft 1250hr Overhaul, Introduction of	6/30/2009 0	Complied With	X			BHTI
ASB 407-01-46 10/12/2001	Reducer AS5174D0604 & Tube Assy 407-076-018-101 to ensure unrestricted hydraulic fluid flow throughsoldnoid valve, Introduction of	6/30/2009 0	Complied With	X			BHTI
ASB 407-01-47 Rev C 7/19/2002	T/R D/S Bearing 406-040-339-ALL, 407-340-339-101 & -103 Supersedes TB 407-98-12 & ASB 407-00-35 AMOC for AD 2002-06-52 para (4)(4)	6/30/2009 0	Cancelled and Superseded by ASB 407-04-63	X			BHTI
ASB 407-01-48 Rev C 4/25/2002	Tailboom Assy 407-030-801-101/-105/-107, Modification of and New Airworthness Limitation/Inspection Schedule, Introduction of	6/30/2009 0	Not Applicable	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-02-49 Rev A 3/12/2002	Downwind Hover Limitation, Introduction of	6/30/2009 0	Not Applicable	X			BHTI
ASB 407-02-50 Rev A 1/17/2003	Aft Crosstube Assy, 407-050-202-10, Inspection of and New Crosstube Assy -103 Introduction of	6/30/2009 0	Complied With	X			BHTI
ASB 407-02-51 3/18/2002	Compressor Wash Tubing Assy and Clearance Check of Firewall Covers with Main Driveshaft, Replacement of	6/30/2009 0	Complied With	X			BHTI
ASB 407-02-52 3/20/2002	Horizontal Stabilizer Slats, 407-023-001-103, Introduction of	6/30/2009 0	Complied With	X			BHTI
ASB 407-02-53 6/5/2002	Tailboom Assy 407-030-801-105/-107 and T/R Gearbox Support Casting 406-030-121-105, Inspection of	6/30/2009 0	Not Applicable	X			BHTI
ASB 407-02-54 Rev A 10/10/2002	Oil Cooler Inlet Airflow, Improvements to	6/30/2009 0	Complied With	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-02-55 10/29/2002	One Time Check of Swashplate Drive Link Cupo Washers, 406-010-412-101	6/30/2009 0	Complied With	X			BHTI
ASB 407-02-56 12/5/2002	Tail Rotor Blades 407-016-001-101 and 406-016-100-119 One Time Leak Check	6/30/2009 0	Complied With	X			BHTI
ASB 407-03-57 Rev B 2/5/2003	Tail Rotor Gearbox Case 406-040-406-109/-113, Oil Feed Hole for Duplex Bearing 406-040-432-103, Addition of	6/30/2009 0	Complied With	X			BHTI
ASB 407-03-58 6/13/2003	Rolls-Royce Corporation 250-C47 Series	6/30/2009 0	Complied With	X			BHTI
ASB 407-03-59 10/15/2003	All Forward and Aft Crosstube Assemblies, Part Numbers as Described Below, Assignment of RIN	6/30/2009 0	Complied With	X			BHTI
ASB 407-03-60 9/4/2003	Rolls-Royce Corporation 250-C47B Engine, Fuel and Control-Release of New Electronic Control Uit (ECU)	6/30/2009 0	Complied With	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-03-61 11/21/2003	Rolls Royce 250-C47B Engine, Turbine Assembly- Inspection of 4th Stage Turbine Wheels (23066744)	6/30/2009 0	Complied With	X			BHTI
ASB 407-04-62 1/7/2004	Rolls-Royce Corporation 250-C47B Engine, Fuel and Control-Hydromechanical Unit (HMU) - Incorporate Dual Element PLA Potentiometer	6/30/2009 0	Complied With	X			BHTI
ASB 407-04-63 Rev B 2/10/2004 Rev 9/5/06	Tail Rotor Driveshaft Bearing 407-340-339-101/-103, Replacement of	6/30/2009 0	Complied With	X			BHTI
ASB 407-04-64 Rev A 3/10/2004 Rev 9/3/04	Engine, turbine Section - Inspection of Rolls-Royce Model 250-C47B Third Stage Turbine Wheels (6898663)	6/30/2009 0	Complied With	X			BHTI
ASB 407-04-65 Rev A 3/22/2004 Rev 6/8/05	Power Turbine RPM (Np) Steady State Operation Avoidance, Introduction of	6/30/2009 0	Cancelled and Superseded by ASB 407-05-67	X			BHTI
ASB 407-04-66 Rev A 7/19/2004 Rev 12/1/04	Freewheel Aft Bearing Cap 406-040-509-101, Inspection and Rework of	6/30/2009 0	Complied With	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-05-67 6/8/2005	New transient Limit and Power Turbine RPM (Np) Steady State Operation Avoidance, Introduction of	6/30/2009 0	Complied With	X			BHTI
ASB 407-05-68 6/30/2005	Rolls-Royce 250-C47B Engine Gearbox Assembly - Inspection and Rework of Gearbox Housing	6/30/2009 0	Complied With	X			BHTI
ASB 407-05-69 7/5/2005	Engine, Fuel and Control - Hydromechanical Unit (HMU) Procedures for Checking P1 Nozzle Screen for Contamination	6/30/2009 0	Complied With	X			BHTI
ASB 407-05-70 Rev A 10/17/2005 Rev 11/10/05	clevis Assembly - Hydraulic Servo Assemblies, Part Number 41011300 and 41011400	6/30/2009 0	Complied With	X			BHTI
ASB 407-06-71 1/10/2006	Main Rotor Hydraulic Servo Actuator Part Number Verification of	6/30/2009 0	Complied With	X			BHTI
ASB 407-06-72 9/12/2006	Horizontal Stabilizer 407-023-801-109, Inspection and replacement of	6/30/2009 0	Not Applicable by Part Serial Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-06-73 10/12/2006	Engine, Turbine Assembly - Power Turbine Outer Shaft	6/30/2009 0	Not Applicable by Engine Serial Number Installed	X			BHTI
ASB 407-06-74 12/22/2006	Product Improvement - Driveshaft Installation Tool SKSP1425-1	6/30/2009 0	Complied With	X			BHTI
ASB 407-07-75 3/27/2007	Cargo hook stress corrosion cracks (Onboard systems service bulletin No. 159-017-00)	6/30/2009 0	Not Applicable by Cargo Hook Part Number	X			BHTI
ASB 407-07-76 4/10/2007	Inspection of Disc Assembly P/N 407-340-340-103	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-07-77 REV A 8/30/2007	Inspection of Tailboom Assembly 407-030-801-107, 407-530-014-101/-103 with upper skin removed or replaced	6/30/2009 0	Not Applicable by Part Number	X			BHTI
ASB 407-07-78 4/17/2007	Verification of Aeronautical Accessories, Inc. Emergency Pushout Windows pushout forces	6/30/2009 0	Not Applicable by Part Number	X			BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-07-79 7/27/2007	Installation procedures improvements of freewheel aft seal P/N 209-340-265-103	6/30/2009 0	Complied With		X		BHTI
ASB 407-07-80 8/27/2007	Tailboom assembly 407-030-801-107 and 407-530-014-101/-103, new inspection requirements	6/30/2009 0	Not Applicable by Part Number	X			BHTI
ASB 407-07-81 9/19/2007	T/R Blade Assy Inspection of	6/30/2009 0	Not Applicable by Serial Number	X			BHTI
ASB 407-08-82 Rev A 11/17/2008	NG Limitation at a Given Temperature, Above 10000 Ft Decal, Addition of	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-08-83 5/19/2008	Hydraulic Pump Driveshaft Assembly 406-040-072-105, One Time Inspection of	6/30/2009 0	Complied With				BHTI
ASB 407-08-84 8/18/2008	Tailboom Assembly 407-030-801-201, 408-030-801-203 and 407-030-801-205 New Inspection Requirements	6/30/2009 0	Complied With		X		BHTI

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-09-85 3/10/2009	One Time Inspection of Lever Assembly P/N 407-001-320-105 and 407-001-320-109.	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-09-86 3/1709	Inspection of Vertical Fin Assembly 206-020-113-233	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-09-87 3/27/2009	One Time Inspection of Anti-Drive Link Assembly P/N 406-010-432-101.	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-09-88 4/7/2009	One Time Inspection of Staked Bearings	6/30/2009 0	Not Applicable by Aircraft Serial Number	X			BHTI
ASB 407-09-89 4/29/2009	One Time Inspection of Tail Rotor Gearbox Part Number 406-040-400-ALL and Tail Rotor Gearbox Case Assembly Part Number 406-040-406-ALL.	3/16/2010 9.5	Complied With	X			██████████
ASB 407-09-90 11/3/2009	Inspection of Hydraulic Servoactuator	3/16/2010 9.5	Complied With	X			BHT ██████████

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT


MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-09-91 12/17/2009	Inspection of Hose Assembly	3/16/2010 9.5	Complied With	X			BHT [REDACTED]
ASB 407-10-92 4/26/2010	Inspection of Tail Rotor Blades	4/29/2010 11.8	Complied With	X			BHT [REDACTED]
ASB 407-10-93 5/3/2010	Replacement of Tailboom Attachments Hardware	12/20/2010 1650	Complied With		X		[REDACTED]
ASB 407-11-94 2/8/2011	Inspection on the Main Rotor Mast Assembly in the area where the Main Rotor Lower Cone Clamps	2/21/2012 571.9	Complied With		X		[REDACTED]
ASB 407-11-95 Rev. A 8/12/2011	Inspection of Upper Left Longeron and Spare Assemblies	7/12/2011 346.4	Not Applicable to this Aircraft at this time. Aircraft has less than 1200 hours		X		Benjamin Knoepke [REDACTED]
ASB 407-11-96 Rev. B 8/29/2011	Perform a one time inspection prior to next flight of Clevis Assembly - Hydraulic Servo Assemblies part numbers: 206-076-062-105 and 206-076-062-107	7/1/2011 331.9	Not Applicable to Aircraft	X			Benjamin Knoepke [REDACTED]

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.

ASB's LISTING
S/N: 53959 REG #N445MT

MODEL: BELL 407

NUMBER	SUBJECT	DATE & HOURS @ COMPLIANCE	METHOD OF COMPLIANCE	ONETIME	RECURR	NEXT COMPLIANCE DATE/HOURS	AUTHORIZED SIGNATURE & NUMBER
ASB 407-11-97 6/30/2011	Installation of Crew Seat Clip Retainers	5/25/2012 678.6	Complied With	X			Todd Moore 

NOTE: AD's / ASB's / TB's MUST be signed off individually on compliance in appropriate logbook.