



Highway Factors Photographs

Tempe, Arizona

HWY18MH010

(21 pages)



Highway Photo 1 – View of the pedestrian’s travel path into the median separating North and South Mill Avenue. Note the concrete sidewalk changes to a dirt path where the shadow of the overhead bridge begins in the photo.



Highway Photo 2 – Continued view of pedestrian’s path in the median toward N. Mill Avenue. Note the sign facing outward in the left side of the photo that prohibits pedestrians from crossing S. Mill Avenue into the median area.



Highway Photo 3 – Close-up view of the wording on the sign.



Highway Photo 4 – View of Uber Vehicle’s approach path to the accident area.



Highway Photo 5 – Pedestrian’s path through the landscaped median to where she crossed into N. Mill Avenue.



Highway Photo 6 – View of where the pedestrian exited the median to cross N. Mill Avenue. Note the sign prohibiting pedestrian crossing in the area is facing the opposite direction. Tempe Public Works will be adding double side signs so that pedestrians coming into the area from under the bridge will have additional signs to guide them to the crosswalk at Washington St./ Curry Road.



Highway Photo 7 – View to the pedestrians right where the Uber vehicle approached from.



Highway Photo 8 – View looking to the west at North Mill Avenue, showing the median area, and South Mill Avenue. In the bottom of the photo are two squares marking the location of drainage inlets. The impact occurred nearest the inlet on the left in the photo, approximately 5 feet west of the solid white line. Also, the impact was 22.5 feet prior to the end of the solid white bicycle path line shown in the bottom of the photo.



Highway Photo 9 – Additional view of North Mill Avenue looking where the impact occurred in the right-hand lane perpendicular to the drainage inlet on the left in the photo.



Highway Photo 10 – Area where the pedestrian entered North Mill Avenue moving toward the drainage inlets on the right side of the photo.



Photo 11 – (Photos 11-20 Courtesy of Tempe Police Department) This photo depicts just north of the impact area with medical debris in the right-hand lane and the bicycle laying where the right turn lane begins.



Photo 12 – Additional view of accident scene the night of the accident.



Photo 13 - View of postcrash scratches in the pavement, smear marks from the victims clothing, and medical debris along with the bicycle in the background.



Photo 14 – Closer view of the victims clothing smears in the right-hand lane and the bicycle laying in the right-hand turn lane against the curb.



Photo 15 – View of victims clothing and medical debris in the right-hand lane followed by the bicycle and then the Uber vehicle in the right-hand turn lane.



Photo 16 – Close-up view of the black and orange bicycle the pedestrian was walking across the road at impact.



Photo 17 – View of Uber Vehicle at final position following the impact.



Photo 18 – View of the damage from the impact on the right front of the Uber/Volvo.



Photo 19 – View of impact area at bottom of photo 5 feet to the left of the solid white bicycle lane line. In the far background evidence tags are placed by debris areas.



Photo 20 – View showing bicycle matched up to the damaged areas on the Uber/Volvo.