

Attachment IV
(Figures 4-7)

Diagram of feature locations




Figure 4: Summary of ILI data for the ruptured pipe joint provided by PII




Figure 5: Summary of MFL and USCD ILI data for the ruptured pipe joint (part 1/2) provided by Enbridge.




Figure 6: Summary of MFL and USCD ILI data for the ruptured pipe joint (part 2/2) provided by Enbridge.




Figure 7: Summary of UT and USCD ILI data for the ruptured pipe joint provided by Enbridge.