

**MP 608 – Marshall, Michigan Incident
NTSB/PHMSA Information Request No. 23**


23.1 Reference: August 4, 2010 request from Darren Lemmerman, PHMSA Engineer


Preamble:

Request: Please provide correlated anomaly data related to the 4 most current ILI runs. Correlate them by stationing and orientation. I would suspect that this is something that Enbridge does normally so use your normal format. This should cover all pipe sections that will be observed at this dig site.


Response: Line 6B Integrated Feature Listing 217710 to 217730.pdf

GW 217710







GW 217720





- Metal Loss -UT
- Metal Loss -MFL
- Crack-like USCD
- ML USCD
- Girth Weld
- Long Seam Weld

GW 217720



GW 217730



GW 217730

