

ANC06FA018

Photo 12



View of fire damaged right side of engine after removal from the airframe