


ANC06FA018

Photo 15



View of fractured and damaged stator vanes.