



Interior corrosion repair spots inboard of cradle pad termination adjacent to shell crack, August 31, 2016.