



Photo 1 – View of Helicopter as Found Relative to Landing Runway (Medford FD)



Photo 2 – View of Main Wreckage as Found (Lycoming Engines)



Photo 3 – View of Main Wreckage with Carburetor in Foreground (Lycoming Engines)



Photo 4 – View of Throttle Control Arm of Carburetor with externally-threaded portion of the two-piece throttle control tie rod still attached to the throttle arm. (Lycoming Engines)




Photo 5 - View of internally-threaded portion of the two-piece throttle control tie rod still attached to the throttle control bellcrank. (Lycoming Engines)



Photo 6 - Photo 5 - View of cellulose material (wood) imbedded in internally-threaded portion of the two-piece throttle control tie rod still attached to the throttle control bellcrank. (Lycoming Engines)




Photo 7 – View of throttle control system after recovery from crash site and wreckage. (Lycoming Engines)



Photo 8 – Overhead view of wreckage in proximity to approach end of Runway 01. (Medford FD)