



Photo 1 – Main wreckage, front view



Photo 2 – Right main gear collapse



Photo 3 – Fractured landing gear