



**Photo 1 - Digital Photograph Provided by Operator. Right side view of the Accident Airplane.**



**Photo 2 - NTSB Digital Photograph. View depicting the first impact crater and the energy path of the airplane with the wreckage in the background.**



**Photo 3 - NTSB Digital Photograph. View of the energy path taken from the impact crater containing glass fragments.**



**Photo 4 - NTSB Digital Photograph. View depicting the separated vertical stabilizer, rudder, and attached rudder trim tab, with wreckage in the background.**



**Photo 5 - NTSB Digital Photograph. View depicting the resting position of the inverted wing and fuselage section of the main wreckage.**



**Photo 6 - NTSB Digital Photograph. Another view depicting the resting position of the inverted wing and fuselage section of the wreckage.**



**Photo 7 - NTSB Digital Photograph. View depicting the inverted wing and fuselage. Note the attached right engine and partially deployed upper and lower right thrust reverser clamshell doors.**



**Photo 8 - NTSB Digital Photograph. View depicting the left engine upper and lower thrust reverser clamshell doors.**





**Photo 9 - NTSB Digital Photograph. View of the throttle quadrant.**



**Photo 10 - NTSB Digital Photograph. View of the right side of the throttle quadrant.**



**Photo 11 - NTSB Digital Photograph. Close-up View of the Right Engine Thrust Reverser Piggy Back Lever and Adjacent Portion of Throttle Quadrant. Note the impact signature aft of the deploy detent.**