



Photo 1 – NTSB Digital Photograph. View Depicting the Contacted Tree.



Photo 2 – NTSB Digital Photograph. View Depicting Broken Tree Branch at Base of Impacted Tree.



Photo 3 – NTSB Digital Photograph. View Depicting Airplane Debris at Base of Impacted Tree.



Photo 4 – NTSB Digital Photograph. View Depicting Recovered Wreckage as First Viewed by NTSB.



Photo 5 - NTSB Digital Photograph. Front View Depicting Installed Engine, and Fuselage, with Portion of Right Wing Visible.



Photo 6 - NTSB Digital Photograph. Left Side of Aft Empennage with Left Horizontal Stabilizer, Elevator, Vertical Stabilizer and Rudder.



Photo 7 - NTSB Digital Photograph. Right Side of Aft Empennage with Damaged Right Horizontal Stabilizer, Elevator, Vertical Stabilizer and Rudder.



Photo 8 - NTSB Digital Photograph. View of Portion of Left Wing, Left Aileron, and Recovered Debris in Background.



Photo 9 - NTSB Digital Photograph. View of Right Wing, Right Aileron, and Right Side of Fuselage in Background.



Photo 10 - NTSB Digital Photograph. View of the Fuel Supply System Including Lines from the Fractured Fuel Tank Outlet Fitting, Shutoff Valve, Auxiliary Fuel Pump, Fuel Filter, and Fuel Line to Engine-Driven Fuel Pump.



Photo 11 - NTSB Digital Photograph. View of the Instrument Panel.



Photo 12 - NTSB Digital Photograph. View of the Throttle Quadrant.



Photo 13 - NTSB Digital Photograph. View of the Separated Propeller.