



**Photo 1 –Overview of Main Wreckage (Courtesy of DSP)**





**Photo 2 – View of reconstructed fenestron**





**Photo 3 – Fence with cut**





**Photo 4 – View of Right Engine (Courtesy of Pratt & Whitney Canada)**





**Photo 5 – View of Left Engine (Courtesy of Pratt & Whitney Canada)**





**Photo 6 – View of Attitude Gyro and Housing**