



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19LA224



Photo 1 – View of Airplane from Right Side (Photo Courtesy of Pilot)



Photo 2 – View of Airplane from Left Side (Photo Courtesy of Pilot)



Photo 3 – Cowling Damage (Photo Courtesy of Pilot)



Photo 4 – View of Airplane Nose and Propeller (Photo Courtesy of Pilot)