



Photo 1 –View of airplane at rest (Courtesy of FAA)



Photo 2 – View of tailwheel where it came to rest (Courtesy of FAA)



Photo 3 – View of fractured tailwheel attachment tube (Courtesy of Salvage Company)



Photo 4 – Closer View of Broken Tailwheel Attach Tube (Courtesy of Salvage Company)