



Photo 1 – NTSB Drone Photograph. Google Earth Mosaic of the Accident Site.



Photo 2 - NTSB Digital Photograph. View of the Initial Impact Ground Scar.



Photo 3 - NTSB Digital Photograph. View of a Portion of the Instrument Panel in a Tree.



Photo 4 - NTSB Digital Photograph. View of Charts, Papers, and Wreckage located Adjacent to Road.



Photo 5 - NTSB Digital Photograph. View of Fragmented Wreckage at Accident Site.



Photo 6 - NTSB Digital Photograph. Another View of Fragmented Wreckage at Accident Site.



Photo 7 - NTSB Digital Photograph. Left Side View of Aft Empennage at the Accident Site.



Photo 8 - NTSB Digital Photograph. View of Both Propellers at the Accident Site Following Recovery.



Photo 9 – Continental Aerospace Technologies Digital Photograph. View of the Left Engine Following Recovery.



Photo 10 - Continental Aerospace Technologies Digital Photograph. View of the Right Engine Following Recovery



Photo 11 - Continental Aerospace Technologies Digital Photograph. View of the Right Engine-Driven Vacuum Pump Following Disassembly.