



Photo 1 – View of airplane at rest (Courtesy of FAA)



Photo 2 – View of Bent Engine Mount [the closest one] (Courtesy of FAA)




Photo 3 – View of Left Wing Damage (Courtesy of FAA)