

Installation of Upper/Lower Bolts on MLG Uplock Assembly



ATLANTIC
SOUTHEAST
AIRLINES™

Issue Date: 09/15/11

Exp. Date: 03/15/12

ALERT BULLETIN


Applicability All Atlantic Southeast Maintenance Personnel

Purpose To inform Maintenance Personnel of the possibility of installing the bolts incorrectly in the main landing gear (MLG) uplock.

Synopsis It has been discovered that the upper bolt of the MLG uplock can be installed improperly.

Additional Information

Bombardier released AOM 1307 to notify operators of this event. See the below figure.



#1 - Bolt installed through the Airframe Structure and MLG Uplock.

#2 - Bolt not installed through the MLG Uplock, but Airframe Structure only.

Effective Date Immediately

Action Required When installing a MLG uplock assembly, ensure that you follow the AMM TASK 32-32-05-400-801 and/or Bombardier Task Card precisely.

Contact Contact Technical Support with any questions regarding this bulletin.