

Propeller Logbook

3025 AIRPORT AVENUE, SANTA MONICA, CALIF. 90405-618 PHONE #: 1—800—421-9995

PROPELLER MAINTENANCE RECORD


Hub Model HC-C24R-18F Blade Design F1616 A Diameter 76 Hub Ser No C# 13364 CH19370 Blade Ser Nos No 1 F2093 6 No 1 F2093 6 No 2 F 498 77 No 2 No 3 No 4 No 5 PITCH RANGE High 29 0 PITCH RANGE High Low Feather Reverse Feather Governor Model		I NOT LECEN MAI	MILMANDE NEODID	
Diameter 76" Diameter Hub Ser No £# 13364 CH19370 Hub Ser No Blade Ser Nos Blade Ser Nos No 1 F20936 No. 1 No 2 F 49877 No. 2 No 3 No. 3 No. 4 No 5 No. 5 PITCH RANGE High Low High Feather Reverse Feather Reverse	Hub Model HC	COYR-1BF	Hub Model	
Hub Ser No	Diameter 76	"		
No 1	Hub Ser No CH	13364-CH19370		1000000
No 2 F 49877 No 3 No 4 No 5 PITCH RANGE High 29.0 Low 13.0 High Low Feather Reverse Feather Reverse			Blade Ser Nos	
No 3 No 4 No 5 No 5 No 5 No 5 High Description Pitch Range High Low High Feather Reverse Reverse				-
No 4 No 5 No 5 PITCH RANGE High 29.0 Low 13.0 High Low Feather Reverse Feather Reverse				
High 29.0° Low 13.0 High Low_ Feather Reverse Feather Reverse				
High Low High Low Feather Reverse Feather Reverse	No 5			mended Envi
	High 29.0 Pli	LOW_13.0		TV sidnacith as
Governor Model Governor Model	Feather	Reverse	Feather Reverse	sorbibed bridge
	Governor Model	TOTAL TOTAL TOTAL TOTAL	Governor Model	

804/217 SPON

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES. SERVICE BULLETINS. SERVICE LETTERS. & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
15/03	726.24	T.T. 1803,24 I centify that the	r propeller has
	been in	spected in accordance with	an annual inspection
		determined to be in airwo	
		A-P, IV	
15/05	780,0	I centify this prop his bo	en Inspected IAU
1 1	3.0	an Aunual Inspectionia	nd was found to so
		in Arrworthy Condition	
		45 BD # 7772-06 By Eddy a	evient lung
		Checked that for cracker 06 1815	
1			
and the	8 /7	of superted as per	
1	.0	al superine and	1/1
	10 a	or worthy at Hus Some	
	Eddy a	wreal T. 818.VI.	
	-	as per AD 06/8/5	

108,3



REG NO MODEL S/N PROP MOD PROP S/N	N113TA M20C 3402 HC-C2YR-1BE CH-19370	CHANDLER AVIATOR CHANDLER MUNICON CHANDLER, 20 (480) 732-93	CIPAL WO# AZ TACH	02/26/10 47060 967.63 379.94 L 2066.04	
0,1		AUTHORIZED S			
AD 2009-22 certify that	2-03 Propeller this propeller	hub due at 991.4 Tach. has been inspected in	AUTH NO.	ding edge. I	E
	HC-C2YK-1	BF S/N hub CH-1937 . F49877 TT. 755.52	THE RESERVE OF THE PARTY OF THE	7666A-2	
cted propo	eller Hartzell	HC-C2YK-1BF S/N	CH19370E (verif	y Eddy current	
ction date	and time per	AD 2009-22-03 Tach	n time @ inspection	on 1042.36 Feb. 18	,
	00hr. Tach.				
		ingine maintenance ar	nd reinstalled per	. Mooney Mainten	ance —
IY	this Propelle condition.	er in conjunction with	n an Annual inspe	ection and find to be	be in

Prop AD

N113TA Hartzell Mod. HC-C2YK-1(BF) S/N CH-19370 Tach. 1109.63 TSOH 445.72 TT.2131.83 Propeller was inspected, dressed and lubed per. Mooney service manual BULLETIN/ AD 2009-22-03 Hub eddy current inspection is due @ Tach. 1142.6

I have inspected this Propeller ICW 100 HR / Annual inspection and find it to be in Airworthy condition. Douglas E. Burke A&P prized Signature Certificate Number Service Instruction/Service Advisory Date Overhaul Time