


ATTACHMENT No. 2

11/24/99



Al Yurman
NTSB
Miami, FL

Al,

I have enclosed the information from Jim Tidball on the pre-purchase inspection done by Learjet in Wichita in 1995. Please understand that the following applies:

N/A Not applicable
CW Complied with
✓ Not verified

The squawks that are written up were not corrected per the customer request.

Regards,

Ralph Witzke

Work Order Number [3] [5] [0] [6] [0] [1] [0]		Squawk [0] [1] [9]		Customer Initial [_____]
Functional Test	Employee Number	Inspection Check	Shop Initial [_____]	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
DISCREPANCY ^{4/13} Cabin pressure follows throttles — 2000 ft bump both directions				
CORRECTIVE ACTION				

Work Order Number [3] [5] [0] [6] [0] [1] [0]		Squawk [0] [2] [0]		Customer Initial [_____]
Functional Test	Employee Number	Inspection Check	Shop Initial [_____]	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
DISCREPANCY ^{4/13} R/A engine med. valve does not shift when power is brought up.				
CORRECTIVE ACTION				

Work Order Number [3] [5] [0] [6] [0] [1] [0]		Squawk [0] [2] [1]		Customer Initial [_____]
Functional Test	Employee Number	Inspection Check	Shop Initial [_____]	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
DISCREPANCY ^{4/13} When moving cabin air switch to max flow you get no increase of air flow				
CORRECTIVE ACTION				



Work Order Number <u>35-060-10</u>			Squawk <u>022</u>		Customer Initial: _____
Functional Test			Employee Number	Inspection Check	Notes:
Part Number REMOVED		Serial Number		Part Number INSTALLED	
Serial Number		Serial Number		Serial Number	
DISCREPANCY <u>4/13</u>		With cabin press. at 7 lb. in auto, cabin will not up rate when selecting a higher altitude			
CORRECTIVE ACTION		- Should up rate depending on where rate knob is at. -			

Work Order Number <u>35-060-10</u>			Squawk <u>023</u>		Customer Initial: _____
Functional Test			Employee Number	Inspection Check	Notes:
Part Number REMOVED		Serial Number		Part Number INSTALLED	
Serial Number		Serial Number		Serial Number	
DISCREPANCY <u>4-13-95 Pak</u>		CVR FAILS "SELF TEST"			
CORRECTIVE ACTION					

Work Order Number <u>35-060-10</u>			Squawk <u>024</u>		Customer Initial: _____
Functional Test			Employee Number	Inspection Check	Notes:
Part Number REMOVED		Serial Number		Part Number INSTALLED	
Serial Number		Serial Number		Serial Number	
DISCREPANCY <u>4-13-95 Pak</u>		Aft "No Smoking - SEAT BELT" Light UNLEDGEABLE And has bulbs inop.			
CORRECTIVE ACTION					



Work Order Number <u>35-010-D-10</u>		Squawk <u>LSQ</u>		Customer Initial _____
Functional Test	Employee Number	Inspection Check	Shop Initial _____	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
<p>DISCREPANCY ^H If Emergency exit seal is coming loose.</p>				
<p>(Reseal) CORRECTIVE ACTION</p>				

Work Order Number <u>35-010-D-10</u>		Squawk <u>LSL</u>		Customer Initial _____
Functional Test	Employee Number	Inspection Check	Shop Initial _____	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
<p>DISCREPANCY External emergency exit handle is not painted red.</p>				
<p>CORRECTIVE ACTION</p>				

Work Order Number <u>35-010-D-10</u>		Squawk <u>LSZ</u>		Customer Initial _____
Functional Test	Employee Number	Inspection Check	Shop Initial _____	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
<p>DISCREPANCY Main cabin door seal is smashed at split line area.</p>				
<p>CORRECTIVE ACTION</p>				



Work Order Number <u>3506010</u>		Squawk <u>168</u>		Customer Initial _____
Functional Test	Employee Number	Inspection Check	Shop Initial _____	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
DISCREPANCY <i>Borkel</i> 4/17/95 C/W AD 89-06-01 SWITLICK LIFE PRESERVERS				
CORRECTIVE ACTION				

Work Order Number <u>3506010</u>		Squawk <u>169</u>		Customer Initial _____
Functional Test	Employee Number	Inspection Check	Shop Initial _____	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
DISCREPANCY <i>Borkel</i> 4/17/95 C/W AD 93-04-02 ROCKWELL TDR-94D MODE 5 TRANSPONDERS				
CORRECTIVE ACTION				



Work Order Number <u>3506010</u>		Squawk <u>170</u>		Customer Initial _____
Functional Test	Employee Number	Inspection Check	Shop Initial _____	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	
DISCREPANCY <i>Borkel</i> 4/17/95 C/W AD 94-26-01 OUTFLOW/ SAFETY VALVES PER SB 35-21-19				
CORRECTIVE ACTION				

Work Order Number <u>3506010</u>		Squawk <u>195</u>		Customer Initial []
Functional Test	Employee Number <u>Eden 4/19</u>	Inspection Check <u>[initials]</u>	Notes	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	

DISCREPANCY 4/18 H.W. Smith Make-up screws for aircraft

CORRECTIVE ACTION For screws to paint shop 4/18 Eden screws painted & returned to shop

Work Order Number <u>3506010</u>		Squawk <u>196</u>		Customer Initial []
Functional Test	Employee Number	Inspection Check	Notes	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	

DISCREPANCY 4/18 H.W. Smith O² need serviced

CORRECTIVE ACTION

Work Order Number <u>3506010</u>		Squawk <u>197</u>		Customer Initial []
Functional Test	Employee Number	Inspection Check	Notes	
Part Number REMOVED	Serial Number	Part Number INSTALLED	Serial Number	

DISCREPANCY 4/18 H.W. Smith Emergency air needs serviced.

CORRECTIVE ACTION

