

# Attachment 7

## Major Repairs and Alterations

## MAINTENANCE &amp; ENGINEERING

## Major Repair Tracking

## Major Repairs

Add a Repair

Review Repairs

## EA Log

Get a New EA ID

Review Log

## Reports

DTE Report

## FCBS Lists

B737

B757

B767

B777

MD80

## FCAS Lists

B737

B757

B767

## Help

Contents

## Review Major Repairs

MRT #	AC	Date	Description	Location	Damage Type	Repair Type	Status	DTE
025843	5CS	4/16/10	Doubler External	L/H fuselage St...	ImpactAccident	New	Active	OPEN
025207	5CS	3/12/10	Other	LW and RW upper...	Corrosion	New	Active	CLOSED
025144	5CS	3/9/10	Splice Repair	STA 700 at LBL ...	Crack	New	Active	CLOSED
025142	5CS	5/27/93	Other	*Void* invalid...	Unknown	Existing	Removed	NOTREQUIRED
014760	5CS	8/20/08	Splice Repair	str 24L sta 166...	Corrosion	New	Active	OPEN
014671	5CS	8/14/08	Part Replacement	cabin A zone #2...	Corrosion	New	Active	NOTREQUIRED
014670	5CS	8/14/08	Part Replacement	A zone #1 seat ...	Corrosion	New	Active	NOTREQUIRED
014668	5CS	8/14/08	Doubler External	station 1720 LB...	Corrosion	New	Active	NOTREQUIRED
014648	5CS	8/13/08	Doubler External	station 1720 RB...	Corrosion	New	Active	NOTREQUIRED
014646	5CS	8/13/08	Doubler External	station 1720 LB...	Corrosion	New	Active	NOTREQUIRED
007668	5CS	9/24/07	Other	R/H Winglet Ins...	NotBlueprint	New	Active	CLOSED
007667	5CS	9/24/07	Other	L/H Winglet Ins...	NotBlueprint	New	Active	CLOSED
005478	5CS	8/14/00	Part Reinforcement	STA 1825 S6R ha...	NotBlueprint	Existing	Active	TBD
005477	5CS	8/11/00	Part Reinforcement	Floor beam STA ...	Corrosion	Existing	Active	CLOSED
005476	5CS	8/11/00	Part Reinforcement	Floor beam STA ...	Corrosion	Existing	Active	CLOSED
005475	5CS	8/11/00	Other	RH strut door	Wear	Existing	Active	CLOSED
005474	5CS	3/31/99	Other	RH MLG jury bea...	NotBlueprint	Existing	Active	CLOSED
005473	5CS	3/31/99	SRMChap51	R-1 door extern...	Wear	Existing	Active	CLOSED
005472	5CS	12/17/97	SRMChap51	R-1 door handle...	Wear	Existing	Active	CLOSED
005471	5CS	12/17/97	SRMChap51	L-1 door handle...	Wear	Existing	Active	CLOSED
005470	5CS	11/15/96	SRMChap51	Aft cargo door ...	Corrosion	Existing	Active	CLOSED
005469	5CS	11/13/96	SRMChap51	Floor beam STA ...	Corrosion	Existing	Active	CLOSED
005468	5CS	11/13/96	SRMChap51	Intercoastal flo...	Corrosion	Existing	Active	CLOSED
005467	5CS	11/13/96	Part Reinforcement	Floor beam STA ...	Corrosion	Existing	Active	CLOSED
005466	5CS	11/13/96	SRMChap51	R-4 door handle...	Wear	Existing	Active	CLOSED
005465	5CS	11/8/96	Part Reinforcement	Floor beam STA ...	Corrosion	Existing	Active	CLOSED
005464	5CS	11/8/96	Part Reinforcement	Floor beam STA ...	Corrosion	Existing	Active	CLOSED
005463	5CS	11/8/96	Part Reinforcement	Floor beam STA ...	Corrosion	Existing	Active	CLOSED
002672	5CS	2/19/07	Doubler External	sta 441 -442 be...	Unknown	Existing	Active	TBD

002671	5CS	2/19/07	Doubler External	sta.480 str.5L ...	Unknown	Existing	Active	TBD
--------	-----	---------	------------------	--------------------	---------	----------	--------	-----

Copyright © 2011 American Airlines, Inc. All rights reserved.