



Materials Laboratory 15 - Exhibit No. 15A Photo 2. Fatigue crack region on the cut-out piece. The bracket indicated mechanical damage, and the arrowheads indicate origin areas, and the extent of preexisting cracking is indicated by the dashed line. (3X)