



Materials Laboratory 15 - Exhibit No. 15A - Photo 5.
SEM photograph of a fracture area containing a fatigue
striation pattern.