



Materials Laboratory 15 - Exhibit No. 15A - Photo 6.  
SEM photograph of a fracture area containing a fatigue  
striation pattern. (1,330X)