

Read Leah

From: Epperson Joe
Sent: Tuesday, May 10, 2016 4:25 PM
To: Read Leah
Cc: Budinski Michael
Subject: Fuel Pump, ERA15LA283

Iuka, MS
Cessna 195A
7/26/2015
ERA15LA283

Leah Read

The subject Fuel pump was visually examined in the Materials Laboratory. The threaded brass pipe adapter on one side of the pump was fractured. Optical examination of the fracture face with the aid of a stereo microscope revealed a rough matte surface texture with features indicative of an overstress separation. No indications of preexisting cracking or corrosion were visible.