

M7	4015	03-Feb-15	TOILET	TOILET TROUBLE	REPAIRED	AIR SUPPLY FAULT; CYCLED TO	04-Feb-15	COMPLETED
M7	4020	03-Feb-15	POWER	THIRD RAIL SHOES	REPAIRED	R1 SHOE MISSING. HM RENEW	04-Feb-15	COMPLETED
M7	4021	03-Feb-15	POWER	THIRD RAIL SHOES	REPAIRED	L1 SHOE MISSING. HM RENEW	04-Feb-15	COMPLETED
M7	4029	25-Jan-15	TOILET	LAVATORY DOOR DEFECTIVE	INCOMPLETE	DOOR IS NOT MAKING CONTACT WITH SWITCH THAT		IN-SERVICE DEFECT
M7	4029	28-Jan-15	TOILET	LIGHT INOPERATIVE	INCOMPLETE	Exterior, Light fixture - Not working, occupied light fi		IN-SERVICE DEFECT
M7	4031	01-Feb-15	TOILET	TOILET TROUBLE	INCOMPLETE			IN-SERVICE DEFECT
M7	4058	03-Feb-15	POWER	THIRD RAIL SHOES	REPAIRED	R1 MISSING. HM RENEWED & C	04-Feb-15	COMPLETED
M7	4070	03-Feb-15	UNIT/CONSIST	UNIT/CONSIST TROUBLE	NO DEFECT FOUND	WHEEL DIAMETER DIFFERENCE	05-Feb-15	COMPLETED
M7	4074	29-Jan-15	CONTROLS	TRAIN OPERATOR DISPLAY	INCOMPLETE	TOD DEFECTIVE		IN-SERVICE DEFECT
M7	4082	03-Feb-15	C/S & ATC	C/S & ATC TROUBLE	NO DEFECT FOUND	NO DEFECT IN THIS CAR - SEE N	04-Feb-15	COMPLETED
M7	4087	13-Jan-15	TOILET	LAVATORY DOOR DEFECTIVE	INCOMPLETE	BATHROOM DOOR WILL NOT LATCH OPEN. MISSING		IN-SERVICE DEFECT
M7	4102	03-Feb-15	POWER	THIRD RAIL SHOES	INCOMPLETE	R-1 CONTACT SHOE BROKEN.		IN-SERVICE DEFECT
M7	4105	03-Feb-15	POWER	THIRD RAIL SHOES	INCOMPLETE	L-2 CONTACT SHOE MISSING.		IN-SERVICE DEFECT
M7	4132	03-Feb-15	LIGHTING	LIGHTING TROUBLE	INCOMPLETE	DEFECTIVE HEADLIGHT SWITCH		IN-SERVICE DEFECT
M7	4165	26-Jan-15	TOILET	NEEDS SERVICE	SERVICED	BATHROOM NEEDS TO BE WAT	05-Feb-15	COMPLETED
M7	4167	02-Feb-15	DOORS	DOOR TROUBLE	NO DEFECT FOUND	R-1 DOOR L/O. RNDF HM YARD	04-Feb-15	COMPLETED
M7	4177	03-Feb-15	UNIT/CONSIST	UNIT/CONSIST TROUBLE	INCOMPLETE	TOD SCREEN LOG FAULT LOCO HAULAGE FAULT.		IN-SERVICE DEFECT
M7	4207	02-Feb-15	TOILET	TOILET TROUBLE	INCOMPLETE	BAD WATER PUMP		IN-SERVICE DEFECT
M7	4210	03-Feb-15	PROPULSION	PROPULSION TROUBLE	REPAIRED	DEAD TRUCK PROPULSION FAL	04-Feb-15	COMPLETED
M7	4231	03-Feb-15	TOILET	ODOR	INCOMPLETE	Toilet - Odor problem		IN-SERVICE DEFECT
M7	4311	29-Jan-15	DOORS	THRESHOLD WELDMENT WITH HEATER	INCOMPLETE	L1 THRESHOLD GROUNDED		IN-SERVICE DEFECT