



MEMORANDUM

Arnold W, Scott
Senior Air Safety Investigator
Central Region

During the examination of the wreckage, all components were accounted for, including both main rotor blades, the engine, and all 3 blades of the pusher-type propeller. No pre-accident anomalies were noted. Due to the extent of fire damage, flight control continuity could not be established with any degree of certainty.