



Metallurgical Group- Picture 15 Masked fracture faces and adjacent surfaces during grit blasting at the NTSB Ashburn, Virginia facility.