



Metallurgical Group- Picture 16 Metallurgical team members inspect the finish from early grit blasting of the ruptured pipe (piece b) at the NTSB Ashburn, Virginia facility.