



Metallurgical Group--Picture 18 Sample sections are cut from the ruptured pipe piece at the NTSB Ashburn, Virginia Facility